
PROCESS CONTROL PLATFORM

Procontrol P14

Flash memory on 83SR50, 83SR51 & 81EU50 is not writable

Product bulletin

Doc. ID	Revision	Status	Author	Approver	Date
8VZZ001689T0001	A	Draft	Christopher Gerlach	Johannes Keilmann	2019-04-15

Executive summary

A hardware issue regarding a Flash PROM on the P14 modules 81EU50R1210, 83SR50R1210 and 83SR51R1210 exists on modules with production date after October 2018.

This product bulletin describes which actions are necessary to identify affected modules and projects.

It further describes which possibilities are available to overcome or solve the problem.

1 Products concerned

The following P14 products are affected:

- 81EU50R1210
- 83SR50R1210
- 83SR51R1210

1.1 Effective date

Devices with production date after October 2018 may be affected.

1.2 Reference documents

N/A

2 Product issue number

TFS ID	Title	Description
208750	Defekte 83SR50 Karten (Defective 83SR50 modules)	<p>Während der leittechnischen Erneuerung eines Anlagenteiles sind neue 83SR50 Geräte geliefert worden. Die Geräte wurden geladen, aber nachher könnte man mit der PDAS nicht mehr auf die Karte zugreifen. Beim Aufrufen des Gerätes mittels PDAG (STR,GER) erscheint die Meldung: "Disable. Kennung nicht gefunden."</p> <p>Die Karten wurden gezogen, und gesteckt.</p> <p>Allen Karten zeigen wieder Störung an (ST und SG).</p> <p>Die Karten sind wieder leer, beim Laden zeigt NOP an.</p> <p>(During the technical renewal of a plant part, new 83SR50 devices were delivered. The devices were loaded, but afterwards you could not access the module with the PDDS. When the device is called up using PDDS (STR, ENG), the following message appears: "Disable, list code not found."</p> <p>The modules were pulled and plugged.</p> <p>All modules show an error again (ST and SG).</p> <p>The modules are empty again, loading shows NOP.)</p>

3 Description

Due to the obsolescence of a Flash PROM (Manufacturer: AMD) on the three modules 81EU50R1210, 83SR50R1210 and 83SR51R1210 the replacement component (Manufacturer: Macronix) was implemented in October 2018.

In one project which was delivered with modules using the new Flash it was discovered that there are problems with writing/reading application programs with PDDS.

Modules are loaded via the PDDS with application programs. These are first written to the RAM. Subsequently, the processing program of the modules copy the application programs from the RAM into the Flash. For the PDDS, however, the process is complete after successfully writing to the RAM and therefore PDDS is not reporting any error.

Copying from RAM to Flash does not or only partly take place. If you try to read back the application program with PDDS it is queried from the Flash. Since there are no data or incorrect data, the error message appears "Disable, list code not found".

When pulling and plugging a module, the application program stored in RAM is deleted because the memory is volatile.

The following steps are necessary to identify if modules are affected:

1. Identify the production date of the modules. This can be done by checking the label on the package or the connector. Or it can be done using GAF/OVE functionality of PDDS.

The label is e.g. printed with the following information:

Ident number	Module Designation	HW-Index	Date code + Serial number
GJR2403800R1210	81EU50R1210	HW-Index: B	K1118 0050

The date code is structured as following: YMMY. (Y=Year, M=Month)


For example, for K1118 0050 production date would be 11/18 (November 2018).



2. Ensure that the modules are affected by checking the equipped type of Flash.


81EU50R1210

Component is located on the top left of the module as shown in the following picture.



83SR50R1210

Component is located on the top left of the module as shown in the following picture.



83SR51R1210

Component is located on the top left of the module as shown in the following picture.




Label of faultless Flash (Manufacturer AMD):

AM29F010B

-70ED


xxxxxxx X

© xxxx AMD



Label of faulty Flash (Manufacturer: Macronix):

MXxxxxxxx
29F040CTI-70G
xxxxxxxxxxx
TAIWAN



4 Corrective action or resolution

If modules are identified which are equipped with the Macronix Flash.



- CAUTION: No changes should be made to the application. The module is running the application program stored in the RAM if no further actions are done via PDDS, KISS or EDS.

Also, the module should not be pulled and plugged. After power off the application program in the RAM is lost.

- Either spare modules can be delivered to the project or the modules can be send directly back to Feeder Factory via normal repair process.

5 Document management

5.1 Revision history

Rev. No.	Rev. Date	Page / Chapter	Revised By	Change Description
A	12-04-2019	all	Christopher Gerlach	Initial version

Visit us

www.abb.com/powergeneration
www.abb.com/water
www.abb.com/symphonyplus

TRADEMARKS

Symphony and Symphony Plus are registered or pending trademarks of ABB S.p.A.

Ability is a trademark of ABB.

All rights to copyrights, registered trademarks, and trademarks reside with their respective owners.

Copyright © 2019 ABB. All rights reserved.

NOTICE

This document contains information about one or more ABB products and may include a description of or a reference to one or more standards that may be generally relevant to the ABB products. The presence of any such description of a standard or reference to a standard is not a representation that all of the ABB products referenced in this document support all of the features of the described or referenced standard. In order to determine the specific features supported by a particular ABB product, the reader should consult the product specifications for the particular ABB product.

ABB may have one or more patents or pending patent applications protecting the intellectual property in the ABB products described in this document.

The information in this document is subject to change without notice and should not be construed as a commitment by ABB. ABB assumes no responsibility for any errors that may appear in this document.

Products described or referenced in this document are designed to be connected and to communicate information and data through network interfaces, which should be connected to a secure network. It is the sole responsibility of the system/product owner to provide and continuously ensure a secure connection between the product and the system network and/or any other networks that may be connected.

The system/product owners must establish and maintain appropriate measures, including, but not limited to, the installation of firewalls, application of authentication measures, encryption of data, installation of antivirus programs, and so on, to protect these products, the network, its system, and interfaces against security breaches, unauthorized access, interference, intrusion, leakage, and/or theft of data or information.

ABB performs functionality testing on the products and updates that we release. However, system/product owners are ultimately responsible for ensuring that any product updates or other major system updates (to include but not limited to code changes, configuration file changes, third-party software updates or patches, hardware change out, and so on) are compatible with the security measures implemented. The system/product owners must verify that the system and associated products function as expected in the environment in which they are deployed.

In no event shall ABB be liable for direct, indirect, special, incidental or consequential damages of any nature or kind arising from the use of this document, nor shall ABB be liable for incidental or consequential damages arising from use of any software or hardware described in this document.

This document and parts thereof must not be reproduced or copied without written permission from ABB, and the contents thereof must not be imparted to a third party nor used for any unauthorized purpose.

The software or hardware described in this document is furnished under a license and may be used, copied, or disclosed only in accordance with the terms of such license.

This product meets the requirements specified in EMC Directive 2014/30/EU and in Low Voltage Directive 2014/35/EU.



The crossed-out wheeled bin symbol on the product and accompanying documents means that used electrical and electronic equipment (WEEE) should not be mixed with general household waste. If you wish to discard electrical and electronic equipment (EEE), please contact your dealer or supplier for further information.

Disposing of this product correctly will help save valuable resources and prevent any potential negative effects on human health and the environment, which could otherwise arise from inappropriate waste handling.