


Product Manual / Spare Parts List

**503 345-502
2000-10-26**

**Power Source
LRC 430**



**ABB Flexible Automation AB
Welding Systems**



The information in this document can be subject to change without prior notice and should not be regarded as an undertaking from ABB Flexible Automation AB. ABB Flexible Automation AB assumes no responsibility for errors that can appear in this document.

ABB Flexible Automation AB is not responsible for damage incurred by the use of this document or software or hardware described in this document.

The document, or parts there of, may not be reproduced or copied without prior permission from ABB Flexible Automation AB. It may neither be imparted to another nor otherwise used without authorisation. Infringement here of will be subject to action in accordance with applicable laws.

Further copies of this document can be obtained from ABB Flexible Automation AB at current prices.

© ABB Flexible Automation AB

Article number: 503 345-502

Date: 2000-10-26

ABB Flexible Automation AB

Welding Systems

S-695 82 Laxå

Sweden

List of Contents

	Page
1 Safety	5
2 Introduction	7
2.1 Communication.....	7
2.2 Equipment.....	7
3 Technical data	9
4 Installation	11
4.1 Placing	11
4.2 Lifting instructions.....	11
4.3 Electrical installation	11
4.4 Main voltage connection.....	13
4.5 Termination unit with resistor.....	13
5 Operation	15
5.1 Controls and connections.....	15
5.2 Thermostat	15
5.3 Overheating protection	16
5.4 Arc voltage feed-back measurement.....	16
5.5 Forced welding stop.....	17
6 Error Messages.....	19
7 Maintenance.....	21
8 Component designation	23
9 Reservdelsförteckning/Spare Parts List LRC 430	27

1 Safety

Users of welding equipment from ABB Flexible Automation AB have the ultimate responsibility for ensuring that anyone who works on or near the equipment observes all the relevant safety precautions. Safety precautions must meet the requirements that apply to this type of welding equipment.

The following recommendations should be observed in addition to the standard regulations that apply to the work place. All work must be carried out by trained personnel well familiar with the operation of the welding equipment.

Incorrect operation of the equipment may lead to hazardous situations which can result in injury to the operator and damage to the equipment.

1 Anyone who uses the welding equipment must be familiar with:

- its operation
- location of emergency stops
- its function
- relevant safety precautions
- welding

2 The operator must ensure that:

- no unauthorized person is stationed within the working area of the equipment when it is started up.
- that no-one is unprotected when the arc is struck

3 The work place must:

- be suitable for the purpose
- be free from draughts

4 Personal safety equipment

- Always wear recommended personal safety equipment, such as safety glasses, flame-proof clothing, safety gloves.
- Do not wear loose-fitting items, such as scarves, bracelets, rings, etc., which could become trapped or cause burns.

5 General precautions

- Make sure the return cable is connected securely.
- Work on high voltage equipment **shall only be carried out by a qualified electrician.**
- Appropriate fire extinguishing equipment must be clearly marked and close at hand
- Lubrication and maintenance must **not** be carried out on the equipment during operation.

LCR 430 is designed and tested in accordance with the international standard EN 50 974-1 (IEC 974-1).

It is the responsibility of the servicing body carrying out service or repair to ensure that the product does not deviate from the above named standard.



WARNING



ARC WELDING AND CUTTING CAN BE INJURIOUS TO YOURSELF AND OTHERS. TAKE PRECAUTIONS WHEN WELDING. FOLLOW YOUR EMPLOYER'S SAFETY DIRECTIONS, WHICH SHOULD BE BASED ON THE MANUFACTURER'S WARNING TEXTS.

ELECTRIC SHOCKS - Can kill

- Install and earth the welding equipment according to applicable standards.
- Do not touch live parts or electrodes with your bare hands or with wet protective equipment.
- Insulate yourself from the earth and work piece.
- Ensure your working stance is safe.

FUMES AND GASES - Can be hazardous to your health

- Keep your head out of the welding fumes.
- Ventilate and extract welding fumes and gases from your working area and the working areas of others.

ARC RAYS - Can injure eyes and burn skin

- Protect your eyes and body. Use a suitable welding helmet and filter lens and wear protective clothing.
- Protect bystanders using suitable screens or drapes.

FIRE HAZARD

- Sparks ("spatter") can cause fires. Therefore make sure that inflammable objects are not in the immediate vicinity.

MALFUNCTION - Contact a skilled technician.


READ AND UNDERSTAND THE OPERATING INSTRUCTIONS BEFORE INSTALLATION AND USE

PROTECT YOURSELF AND OTHERS

2 Introduction

The LRC 430 is a power supply intended for MIG/MAG welding. It is designed for both short-arc, spray--rc and pulsed MIG/MAG welding. The power supply is fan-cooled.

The power supply consists of a power unit and a weld data unit. All operator and machine communication is carried out from the robot's programming unit.



2.1 Communication

All exchanges of information between the welding equipment and the robotics system take place via a CAN bus. This communication is handled by the weld data unit in the LRC 430.

There is a second CAN bus internal to the LRC 430. This internal bus handles all communications between the weld data unit, the power supply and the feeder mechanism. As the wire feeder is sited outside the power supply, the internal bus is not only located within the power supply, but is a functional part of the welding equipment.

2.2 Equipment

The power supply is fitted with a termination resistor.

3 Technical data

	LRC 430	LRC 430
Mains voltage	400 V $\pm 10\%$, 3~ 50/60 Hz	3~50Hz:230/400/500V $\pm 10\%$ 3~60Hz:208/230/460/475/ 575V $\pm 10\%$
Permitted loading at 60 % duty cycle 100 % duty cycle	430 A / 35.5 V 400 A / 34 V	430 A / 35.5 V 400 A / 34 V
No-load power	520 W	520 W
Power factor	0,92	0,92
Efficiency	0,82	0,82
No-load voltage	65-80 V	65-80 V
Primary current I _{1max} I _{1eff}	28.8 A 26.1 A	See table 1 See table 1
Dimensions l x w x h	880x 650 x 845 mm	880 x 650 x 845 mm
Weight	96 kg	141 kg
Insulation class	H	H
Degree of protection	IP 23	IP 23
Application class		

Table 1:

3~50Hz				3~60Hz				
U ₁	230V	400V	500V	208V	230V	460V	475V	575V
I _{1max}	52.8A	28.8A	23.6A	57.2A	51.6A	25.3A	24.5A	20.7A
I _{1eff}	46.1A	26.1A	20.8A	50.8A	45.2A	22.3A	21.8A	18.1A

Duty cycle

The duty cycle refers to the time in per cent of a ten--minute period that you can weld at a certain load without overloading the welding power source.

Degree of protection

The **IP** code indicates the enclosure class, i. e. the degree of protection against penetration by solid objects or water. Equipment marked **IP 23** is designed for indoor and outdoor use.

Application class

The symbol  indicates that the power source is designed for use in areas with increased electrical hazard.

4 Installation

The installation shall be executed by a professional.

⚠️ WARNING!


This product is intended for industrial use. In a domestic environment this product may cause radio interference. It is the user's responsibility to take adequate precautions.

4.1 Placing

Place the welding power source so as not to prevent the cooling air from circulating.


4.2 Lifting instructions



The powersource should only be lifted by means of its lifting eye. The handle is only intended for pulling it along the ground..



4.3 Electrical installation

400 V, 460 V, 475 V, 500 V, 575 V 50/60 Hz





4.4 Main voltage connection

Check that the power supply is connected to the right voltage and that the fuse is of the correct rating.

The device should be earthed in accordance with current regulations in force

Recommended cable area and fuse rating


LRC 430 3~ 50/60 Hz							
Mains voltage	208V	230V	400V	460V	475V	500V	575V
Current 60%	52A	47A	27A	24A	23A	22A	18A
Cable areaa mm²	4x10	4x10	4x4	4x4	4x4	4x4	4x4
Fuse slow-blow *)	50A	50A	20A	20A	20A	20A	20A

*) Valid for slow-blow melting fuses

4.5 Termination unit with resistor

To avoid interference, the two ends of the CAN bus should be fitted with termination resistors. One end of the internal CAN bus is inside the welding data unit, which has a built-in resistor.

The other end is located at the rear side of the power source itself, and, unless the relevant socket is used, it should be fitted with a termination resistor placed according to the following diagram.




5 Operation

General safety regulations for the handling of the equipment appear from chapter 1. Read through before you start using the equipment.

5.1 Controls and connections

- | | |
|--|--|
| 1 Measuring cable connector (XS20)
(voltage feed-back,welding wire/workpiece) | 6 Orange indicator lamp, overheating |
| 2 External CAN-connection (XP4) | 7 White indicator lamp, mains voltage ON |
| 3 Fuse,slow-blow 10 A (42 V connection) | 8 Switch for mains voltage ON/OFF |
| 4 Internal CAN-connection, 42 V (XS22:1) | 9 Connection for welding cable (+) |
| 5 Internal CAN-connection, 42 V (XS22:2) | 10 Connection for welding cable (-) |



5.2 Thermostat

The welding power source is equipped with a thermostat which starts the cooling fan when the temperature has reached a certain level. On overload or on fan breakdown the overheating cut-out comes into action. The overheating cut-out only comes into action on overload and on fan breakdown.

5.3 Overheating protection

The power supply is equipped with a thermal switch which triggers if the temperature becomes too high. When this happens, the current is interrupted and an orange indicator lamp shines on the front of the power source. When the temperature falls, the thermal switch automatically resets.

5.4 Arc voltage feed-back measurement

The arc voltage can be measured in two ways:

Alternative 1

Measuring between the welding wire (+) and the power source welding outlet (OKC -). Welding wire positive polarity, welding outlet negative.

Connections to terminal board X202		
Necessary external connections		Explanation of existing connection on power supply
	6	Welding negative, detector
	5	Welding negative from OKC (minus) socket.
	7	Welding positive from welding wire in feeder unit.
	3	Forced welding stop. Open circuit between 3 and 4 means stop.
	4	


Alternative 2A

Measurement between welding wire (+) and workpiece (-). Welding wire positive polarity, workpiece negative.

Connections to terminal board X202		
Necessary external connections		Explanation of existing connection on power supply
	6	Welding negative, sensing workpiece.
	5	
	7	Welding positive from welding wire in feeder unit.
	3	Forced welding stop. Open circuit between 3 and 4 means stop.
	4	

Alternative 2B

Measurement between welding wire (-) and workpiece (+). Welding wire negative polarity, workpiece positive.

Connections to terminal board X202		
Necessary external connections		Explanation of existing connection on power supply
	7	Welding positive, sensing workpiece
	5	
	6	Welding negative from welding wire in feeder unit
	3	Forced welding stop. Open circuit between 3 and 4 means stop.
	4	

Alternative 2 means that a measurement lead has to be connected to the workpiece. This method produces the most correct arc voltage measurements.

5.5 Forced welding stop

Under normal operation this input should be closed.

NB! In an emergency it is possible to stop the current powersource at once by opening this input. See table above.

6 Error Messages

Error messages are described in User's Guide.

The robot system presents a six digit error code, for example, 117013. The first three digits (117) denotes in which part of the robot system there is a fault, 117 denotes the fault is in the welding equipment. The fourth digit (0) denotes in which part of the welding equipment the fault is located. The two remaining digits (13) denotes the type of fault in the welding equipment.

Code list for units in the welding equipment (fourth digit):

0=Weld data unit AP8 (SLRC)

2=Control unit AP2 (LRC)

3=Wire feed unit PIB (MLRC)

7 Maintenance

Note!

All warranty undertakings given by the supplier cease to apply if the customer attempts to rectify any faults on the machine during the warranty period. Only those persons who have appropriate electrical knowledge (authorised personnel) may remove the protection plates to connect or carry out service, maintenance or repair work on welding equipment.

Cleaning

Check regularly that the power source is free from dirt.

How often, and to what extent, cleaning should be carried out depends on the welding process, arc time, disposition and the surrounding environment. It will normally sufficient to clean the power source by using compressed air (reduced pressure) once a year.

If the power source is very dirty, brushing and vacuuming are recommended.

- Disconnect the welding power source from the mains power supply.
- Remove the adapter from the socket. Lock the socket to prevent unauthorised connection.
At fixed installations, the safety switch should be set to the off position. Lock the switch.
- Remove the power source's protection plates for best access.

After cleaning, all protection plates must be mounted before you connect the power source to the mains supply.


LRC 430 is designed and tested in accordance with the international standard EN 50 974-1 (IEC 974-1).


It is the responsibility of the servicing body carrying out service or repair to ensure that the product does not deviate from the above named standard.

8 Component designation

AP1	Power board
AP2	Control board
AP3	Circuit board EMC
AP4	Shunt (Hall sensor)
AP5	Circuit board EMC
AP8	Weld data board
C1, C7, C8	Capacitor, suppression
C4-C6	Capacitor, fan
EV1, EV2	Fan
FU1-FU3	Fuse
HL1	Indication lamp
L1-L4	Inductor
Q1 - Q2	IGBT-module
QF1	Switch
R2-R4	Resistor
ST1-ST3	Thermal switch
TA1	Current transformer
TC1-TC2	Control transformer
TM1	Main transformer
V1	Diode module
V2	Thyristor module
V3	Indication lamp LED
VC1	Rectifier bridge
XP1-XP3, XP5	Connector
XP4	Pin socket
XS1 - XS17, XS21-XS30	Connector
XS18, XS19	Welding outlet
XS20	Sleeve socket

Scheme





13 Reservdelsförteckning/*Spare Parts List* LRC 430

Gäller för strömkällor med serienummer från och med:

015-XXX-XXXX

Valid for power sources with serialnumber as from:

015-XXX-XXXX

Reservdelar beställs genom ABB Flexible Automation AB. Vid beställning var vänlig uppge typ och tillverkningsnummer samt benämningar och beställningsnummer enligt reservdelsförteckningen.


Rätt till ändring av specifikationer utan avisering förbehålls.

Spare parts are to be ordered from ABB Flexible Automation AB. Kindly indicate type of unit, serial number, denominations and ordering number according to the spare parts list.

Rights reserved to alter specifications without notice.


Positions-nummer Position number	Antal Quantity	Beställningsnummer Ordering number	Benämning	Denomination	Annärkningar Remarks
		0502 990 880	Strömkälla LRC430	Power Source LRC 430	400V,50-60Hz
		0502 990 881	Strömkälla LRC430	Power Source LRC 430	Multivoltage,208-575V,50-60Hz
101	1		Varningsskylt	Sticker	
102	1	0502 990 001	Handtag	Handle	
103	4	0502 990 002	Packning	Seal	
104	1		Lock	Cover	
105	1		Packning	Seal	
106	1		Stödplåt	Support plate	
107	1		Fjädrande Rörpinne	Roll pin	Ø 8x28
108	1		Sidoplåt, vänster	Side panel, left	Med tryck / with text
109	1		Sidoplåt, höger	Side panel, right	Med tryck / with text
110	1		Uttagsmärkning	Terminal marking	
111	2	0502 990 003	Länkhjul	Castor wheel	Ø 125mm h=150mm
112	1		Bygel	Clamp	
113	1		Axel	Shaft	
114	2		Bricka	Washer	Ø 36/21X3
115	2	0502 990 004	Hjul	Wheel	Ø 250mm
116	2	0502 990 005	Låsbricka	Locking washer	
117	1		Blindplugg	Cover, Ø 16	Ø 16
	1		Blindplugg	Cover, Ø 19	Ø 19
	1		Blindplugg	Cover, Ø 30	Ø 30
	1		Blindplugg	Cover, Ø 44	Ø 44
	1		Blindplugg	Cover, Ø 64	Ø 64
	1		Blindplugg	Cover, Ø 31	Ø 31
	1		Blindplugg	Cover, Ø 22	Ø 22
118			Mutter	Nut, M 6/1,8--2	M 6/1, 8-2
119			Snabblåsmutter	Fast lock nut	
120			Uttagsmärkning	Terminal marking	
121	1	0503 232 012	Hylsuttag	Sleeve socket	12-pol, XS20*

* = Komponentens beteckning i kretsschemat/Component designation in the circuit diagram




Positionsnummer Position number	Antal Quantity	Beställningsnummer Ordering number	Benämning	Denomination	Anmärkningar Remarks
201	1	0502 990 006	Kabelavlastning	Cable inlet	
202	1	0503 232 005	Kretskort	Circuit board	EMC, AP5*
	1	0502 990 007	Plint	Terminal	3-pol/3-pole, XT1*
203	2		Distans	Spacer	
204	1	0502 990 008	Kondensator	Capacitor	3µF 400V, C4*
205	1	0502 990 009	Kondensator	Capacitor	6µF 400V, C6*
206	1	0502 990 010	Elkopplare	Switch	Med vred/with knob, QF1*
207	1		Skyddsplåt	Protection cover	
208	1	0502 990 011	Lampa	Light--emitting diode	Gul/yellow, V3*
209	1	0502 990 012	Indikeringslampa	Indicating lamp	Vit/white, HL1*
210	1		Panel	Panel	Med tryck/with text
211	4		Genomföring	Grommet	
212	1		Skyddsplåt	Protection cover	
213	1	0502 990 013	Manövertransformator	Control transformer	TC1*
	1		Säkring	Fuse	2A trög/slow- blow, FU2*
214	1	0502 990 014	Transformator	Transformer	TC2*
	1		Säkring	Fuse	500mA, inkluderat i pos 214/ included in item 214/FU3*.
215	1		Isolation	Insulation board	
216		0503 232 011	Skärmplåt	Screen plate	
217	1	0502 990 015	CAN-kabel, inkl. kontakt- don XP1* och XS28*	CAN-cable, complete with connectors XP1* and XS28	
218			Kabelsats	Cable set	
219	1	0502 990 016	Kretskort	Circuit board	EMC, AP3*
	1		Kontaktdon	Connector	4-pol/4-pole, XS27*
	1		Kontaktdon	Connector	7-pol/7-pole, XS25*
	1		Kontaktdon	Connector	4-pol/4-pole XS28
	2	0503 232 012	Sleeve socket Intern CAN	Sleeve socket Internal CAN	12-pol/12-pole, XS22:1*, XS22:2*.
220	1		Dragavlastning	Clamp	
221	1		Kondensator	Capacitor	0.1µF 250V, C8*
222	1	0502 990 017	Automatsäkring	Circuit breaker	10A, FU1*
	1		Skylt	Sticker	

* = Komponentens beteckning i kretsschemat/Component designation in the circuit diagram



AH 0502


Positionsnummer Position number	Antal Quantity	Beställningsnummer Ordering number	Benämning	Denomination	Anmärkningar Remarks
223	1	0502 990 018	Plint	Terminal	3-pol/3-pole, XT2*
224	1	0503 232 013	Stiftpropp	Pin plug	R4*, 120Ohm, 0,25W 1%, Met- all film
225	3	0503 232 009	Skyddslock	Protection cap	
226	1		Skylt	Sign	
227	1	0503 232 002	Kretskort	Circuit board	Manöverenhet, AP2*
	4		Kontaktdon	Connector	2-pol/2-pole, XS8*, XS15*, XS17*, XS29*
	2		Kontaktdon	Connector	4-pol/4-pole, XS5*, XS12*.
	4		Kontaktdon	Connector	2-pol/2-pole, XS6*, XS7*, XS14*, XS30*.
	2		Kontaktdon	Connector	3-pol/3-pole, XS9*, XS11*.
	1		Kontaktdon	Connector	4-pol/4-pole, XS16*
	1		Kontaktdon	Connector	4-pol/4-pole, XS10*
	1		Kontaktdon	Connector	7-pol/7-pole, XS26*
229			Skydd	Protection	
230	1		Box	Box	
231	1		Lock	Cover	
232	4		Distans	Spacer	



AH 0502


Positionsnummer Position number	Antal Quantity	Beställningsnummer Ordering number	Benämning	Denomination	Anmärkningar Remarks
301	1	0502 990 019	Flerspänningstransformator	Multivoltage transformer	208-575V,3~50/60Hz
302	1		Gavel övre	Front panel	
303	1		Gavel nedre	Front grill	
304	1		Fläktfäste	Fan attachment	
305	1	0502 990 020	Fläkt	Fan	230VAC EV2*
306	1		Distansplåt	Distance sheet	
307	1		Fläktkåpa	Fan mantle	
308	3		Skruv	Screw	M10x25
309	6		Fjäderbricka	Spring washer	Ø 20/10.2x1.1
310	3		Bricka	Washer	Ø 22/10.5x2
311	1		Kondensator	Capacitor	0.1µF 250 V, C1*
312	2		Kabel	Cable	
313	2	0160 362 881	Maskinkontakt	Current terminal	OKC 50, XS18*, XS19*
314	1		Induktor	Inductor	Termovakt ST2 och ST3 är inkluderade/Thermal cutouts ST2 and ST3 are included, L2*
			Termovakt	Thermal cutout	Sluter vid 60°C, öppnar vid 30°C/Closing at 60°C, opening at 30°C, ST2*
			Termovakt	Thermal cutout	Öppnar vid 160°C, sluter vid 130°C/Opening at 160°C, closing at 130°C, ST3*
315	4		Bygel	Clamp	
316	16		Ferritkärna	Ferrite core	
317			Tejp	Tape	För luftgap/for air gap
318	1		Transformatorspole	Transformer coil	TM1*
319	2		Ferritring	Ferrite ring	L3*
320	1		Skena	Bus bar	

* = Komponentens beteckning i kretsschemat/Component designation in the circuit diagram




Positionsnummer Position number	Antal Quantity	Beställningsnummer Ordering number	Benämning	Denomination	Anmärkningar Remarks
401	1	0502 990 021	Motstånd	Resistor	20Ω, 50W, R3*
402	1	0502 990 022	Kondensator	Capacitor	220 µF 250V, C7*
	1		Mutter	Nut	Plastic
403	2		Plastnit	Plastic rivet	
404	1		Isolation	Insulation	
405	1		Isolation	Insulation	
406	2		Clips	Clips	
407	1	0503 232 007	Fläkt	Fan	24 VDC, EV1*
408	1		Induktor	Inductor	L1*
409	1		Isulation	Insulation	
410	8		Ferritring	Ferrite ring	
411	3		Buntband, blå	Cable tie, blue	Värmebeständig /heat resistant
412	5		Diodmodul	Diode module	V1*
-			Kontaktpasta	Thermal compound	För fastsättning av/for fitting of ST1, Q1, Q2, V1, V2 och VC1
413	1		Skena	Bus bar	
414	5		Genomföring	Grommet	
415	1		Skena	Bus bar	
416	1		Skena	Bus bar	
417	1		Skena	Bus bar	
418	1		Termovakt	Thermal cutout	Öppnar vid 80°C,sluter vid 60°C/Opening at 80°C,closing at 60°C,ST1*
419	2		IGBT--module	IGBT--module	Q1*, Q2*
-	2		Kontaktpasta	Thermal compound	För fastsättning av/for fitting of ST1, Q1, Q2, V1, V2 och VC1
420	1		Likriktarbrygga	Rectifier bridge	VC1*
-	1		Kontaktpasta	Thermal compound	För fastsättning av/for fitting of ST1, Q1, Q2, V1, V2 och VC1

* = Komponentens beteckning i kretsschemat/Component designation in the circuit diagram



AH 0505


Positionsnummer Position number	Antal Quantity	Beställningsnummer Ordering number	Benämning	Denomination	Anmärkningar Remarks
421	1		Tyristormodule	Thyristor module	V2*
-	1		Kontaktpasta	Thermal compound	För fastsättning av/for fitting of ST1, Q1, Q2, V1, V2 och VC1
423	4		Distans	Spacer	
424	1	0503 232 001	Kretskort	Circuit board	Pos 431 är inkluderad i kretskortet/item 431 is included in the circuit board, AP1*
-	2		Säkring	Fuse	
-	3		Kontaktdon	Connector	2-pol, XS1*, XS2*, XS4*
-	1		Kontaktdon	Connector	4-pol, XS3*
425			Bricka	Washer	Ø 10/5.3x1
426			Fjäder bricka	Spring washer	Ø 10/5.2x0.5
427			Skruv	Screw	M5x12
428	1		Isolationsbricka	Insulating washer	
429	1		Distans	Spacer	
430	1		Slang	Hose	D11,6/10, 0,025m
431	1		Strömtransformator	Current transformer	TA1*
432	1		Ferritring	Ferrite ring	L4* 4varv/4turns
433	4		Distans	Spacer	
434	1		Shunt	Current sensor	AP4*
435	1		Kontaktdon	Connector	5-pol/5-pole, XS21*
436	1		Skena	Bus bar	
437			Mutter	Nut	M8
438			Fjäderbricka	Spring washer	Ø 16/8.2x0.9
439			Bricka	Washer	Ø 16/8.4x1.5
440	1	0502 990 025	Motstånd	Resistor	R2*
441	1		Kabel	Cable	
442			Skruv	Skrew	M8x30



AH 0505

Positionsnummer Position number	Antal Quantity	Beställningsnummer Ordering number	Benämning	Denomination	Anmärkningar Remarks
501	1		Dragavlastning	Clamp	
502	1		Kondensator	Capacitor	0.1µF / 250 V, C1*
503	1	0503 232 008	Stiftuttag Burndy	Burndy plug	12-pol/12-pole, Inkluderat i pos 510/included in item 510, XP4 External CAN
504	1		Skärmplåt	Screen plate	
505	1		Isulation	Insulation	
506	1		Lock	Cover	
507	1	0503 232 003	Kretskort	Circuit board	Svetsdata/weld- ing data, AP8*
508	1		Nedre box	Bottom box	
	1		Kontaktdon	Connector	2-pol, XS13
509	1	0502 990 023	Kabel Intern CAN	Cable Internal CAN	Kabel komplett med kontaktdon/ cable complete with connectors XP2 och XP3. XP2*, XP3*
510	1	0502 990 024	Kabel Extern CAN	Cable External CAN	Kabel komplett med kontaktdon/ cable complete with connec- tors XP4 och XP5.XP4 and XP5*
511	7		Distans	Spacer	M4x25

* = Komponentens beteckning i kretsschemat/Component designation in the circuit diagram



AH 0503

ABB

**501 345-502
2000-06-19**