



# TOTALFLOW

## *Technical Bulletin 110*

### MicroFLO and XSeries Potential Collection Problem using the Husky FS2 or MP2500

#### Totalflow Technical Bulletin

Version 1.0, Revision AC (12 November 2003)

---

#### ABB Inc.

ABB Inc.  
7051 Industrial Blvd  
Bartlesville, Oklahoma  
74006 USA

Telephone  
Domestic 800 442-3097  
International (918) 338-  
4880  
Telefax (918) 338-4607

Internet  
[www.abb.com/totalflow](http://www.abb.com/totalflow)



## 1. Purpose

To describe a collection problem when using Itronix (formally Husky) FS2 or MP2500 handheld computer to collect data from the Model 6213 MicroFLO or XSeries products.

## 2. Description

Database 2 (DB2) FS2 and MP2500 collections can be corrupted. The corruption is based on the number of the three records (log records, daily records and events) being collected. This problem does **not** occur when using the FS2 or MP2500 to collect data from older style 6400/6700/6600 Flow Computers.

The corruption is caused by the Flow Computer based on the number of events, log records or daily records contained in the Flow Computer at the time of collection. Due to the nature of the problem the events and log records typically cause the failure to occur. In general the problem can occur whenever the events file exceeds 113 records or when the log records exceed 81.





### XSeries

2100825-014 or newer  
2100826-020 or newer  
2100395-016 or newer  
2100805-016 or newer  
2101050-006 or newer  
2101052-006 or newer

ABB has also released Husky FS2 Itronix MP2500 firmware to correct the download problem without necessarily changing Flow Computer FLASH. The following handheld releases correct the problem.

### Itronix (formally Husky) FS2

2018583-008

### Itronix (formally Husky) MP2500

2100329-006