


NOTES:

1. WARNING
Using a non-factory RS232 data cable between UCI2 unit may result in damage and may void system warranty.
2. All installations in hazardous locations must comply with requirements of Certification Drawing 2017275-CD.
3. Dial-Up Modem Configuration Shown. When using dial-up dual port modem, power to be connected to P1-9.

4. Software Scheduler Required



TOTALFLOW
Products

ACTION
D19343

DOC TYPE
UD

TITLE
XRC 6490\6790\6890 COMM 1 (2100355 BD)
TO UCI2 w/EXT SWITCHED POWER (RS-232)

DWG NO.
2102210

REV
AB

SHEET
1 OF 1