

ABB CYLON® TECHNICAL BULLETIN NO. 475

Issue Date: 17 November 2021

CBT-3T6-5R Firmware 9.0.1

Products Affected: CBT-3T6-5R

Summary

The initial release of CBT firmware v9.0.0 under some circumstances caused a reboot loop problem on the CBT-3T6-5R. Firmware v9.0.1 resolves this issue.

Background

Manual upgrades to CBT-3T6-5R over BACnet were reported to cause a serious error if the Strategy was not wiped before upgrade.

Features

Updated firmware version is being made available for CBT-3T6-5R.

Note: CBT12iVAV and CBT-4T4-4T controllers do **not** support the FusionAir Smart Sensor range. Users should not upgrade these controllers to firmware version 9 or later.

Customer Impact

Customers who had downloaded CBT Firmware v9.0.0 must NOT install it on CBT-3T6-5R.

Upgrade directly to v9.0.1 if support for FusionAir Smart Sensors is required.

The firmware can be download from our support web sites:

- North America <https://cyloncommunity.com/>
- Europe/ROW see <http://support.cylon.com/>