

CYLON® TECHNICAL BULLETIN NO. 521

Issue Date: 13 October 2023

FBVi, FBTi, FBXi Firmware 9.2.7

Products Affected: FBXi-X256, FBXi-X48, FBXi-8R8-X96, FBXi-8R8-H-X96, FBTi-7T7-1U1R, FBTi-6T1-1U1R, FBVi-2U4-4T-IMP, FBVi-2U4-4T-SI, FBVi-2U4-4T, FBVi-2U4-4T-FA-IMP, FBVi-2U4-4T-FA-SI

Summary

This is an incremental build from the previous version that fixes reported issues and adds enhancements.

Detail

Note: This firmware release is for the listed products only, and does not include CBXi-8R8 or CBXi-8R8-H

Note: Please ensure that when accessing the controller WebUI the URL must use https:// instead of http://. Also, when using an eXplore touchscreen, please ensure that the URL used in the eXplore configuration uses https://.

RESOLVED ISSUES

- FusionAir/CBT-STAT Sensor function with **FBTi-7T7-1U1R** and **FBTi-6T1-1U1R** controllers.
- The **Sensor/RS-485 port 2** of the **FBXi Series** Modbus function.
- Controller startup error
- Factory reset error

Customer Impact

Customers wishing to use this latest firmware for their controllers can upgrade when as soon as convenient.

The firmware is available from Global SBS Support (global-sbs.support@abb.com) or <https://cyloncommunity.com/> (North America)