

CYLON® TECHNICAL BULLETIN NO. 492

Issue Date: 01 July 2022

CB Line Firmware 9.1.2

Products Affected: CBT-3T6-5R, CBT-4T4-2U1R, CBV-2U4-3T, CBV-2U4-3T-N, CBX-8R8, CBX-8R8H

Summary

Additional parameters have been added to the FusionAir module.

Background

As part of ABB's policy of continuous improvement, FusionAir Smart Sensor capability has been enhanced.

Features

ENHANCEMENTS

- SYSX-580 Added a "Zone Temperature Input" to the FusionAir Module and a configuration setting to display that Zone Temperature value on the FusionAir device in the place of the local sensor's value.
- SYSX-552 Added a "Unitless Input" to the FusionAir sensor's display readouts

RESOLVED ISSUES

- SYSX-403 In Celsius mode the 10K thermistor no longer returns a value of 0.
- SYSX-582 CB-USB Service port operation when download from CXpro no longer gives intermittent invalid response.

Customer Impact

Customers wishing to access the new functionality must upgrade when as soon as convenient.

The firmware can be download from our support web sites:

- North America <https://cyloncommunity.com/>
- Europe/ROW <http://support.cylon.com/>