
ABB MEASUREMENT & ANALYTICS | TECHNICAL BULLETIN

TCl Toolkit dependency on missing OLEDLG.dll on Windows Core OS

AUGUST 1, 2022 | 2108199TB-TB223AA

1. Description

A detected dependency of the TCI Toolkit dll files on OLEDLG.DLL results in a runtime failure on Windows® Core OS systems. The OLEDLG.DLL does not exist in the Windows Core OS. The dependency on OLEDLG.DLL was removed from the TCI Toolkit dll files starting with version 3.13.1 and later.

2. Is your product impacted?

The only known impact of this dependency is on the newer, stripped-down Windows® Core OS when using tcidll.dll or tcidll64.dll from TCI Toolkit versions 3.11 to 3.13.

If you are using TCI Toolkit versions 3.11 to 3.13 and this problem is detected, upgrade to version 3.13.1 or later.



ABB Inc.

Measurement & Analytics

Quotes: US-IAMA.inquiry@us.abb.com

Orders: US-IAMA.order@us.abb.com

Training: US-IAMA.training@us.abb.com

Support: upstream.support@us.abb.com

+1 800 442 3097 (opt. 2)

Additional free publications are available for download at:

www.abb.com/upstream

Main Office - Bartlesville
7051 Industrial Blvd
Bartlesville, OK 74006
Ph: +1 918 338 4888

Texas Office - Houston
3700 W. Sam Houston
Parkway S., Suite 600
Houston, TX 77042
Ph: +1 713 587 8000

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents - in whole or in parts – is forbidden without prior written consent of ABB.

Windows® is a registered trademark of Microsoft.

2108199TB-TB223AA

Copyright© 2022 ABB all rights reserved