



Montasjeveiledning
Installation Instruction
Montageanleitung

XLBM00


Sikrings-lastskillebryter 1P/3P
Fuse-switch disconnecter 1P/3P
Sicherungslasttrennschalter 1P/3P

1SEP408116P0001 Rev. L



Al-ledere børstes og innsettes med fett før tilkobling.
Al- conductors have to be brushed and greased before connection.
Al-Leiter müssen vor den anschliessen geburset und eingefettet werden.

Z-Busbar



DIN Busbar

