

# FBVi, FBTi, FBXi, CBXi Firmware 9.2.4

Products Affected: FBXi-X256, FBXi-X48, FBXi-8R8-X96, FBXi-8R8-H-X96, FBTi-7T7-1U1R, FBTi-6T1-1U1R, FBVi-2U4-4T-IMP, FBVi-2U4-4T-SI, FBVi-2U4-4T, FBVi-2U4-4T-FA-IMP, FBVi-2U4-4T-FA-SI, CBXi-8R8, CBXi-8R8-H

## Summary

This is an incremental build from the previous version that fixes reported issues and adds enhancements.

## Detail

### NEW FEATURES

- A CBXi-8R8(-H) webpage back-up(.tgz) can now be restored on an FBXi-8R8-X96(-H)
- Enhanced the configurability of the FBXi-8R8-X96(-H) serial ports

### RESOLVED ISSUES

- The size of the device list table has been increased to optimize behavior of BACnet ranged Who-Is requests on sites with large numbers of controllers
- FBXi factory restore operation now operates as expected.
- Fixed an issue where in rare cases the controller webpage would not load.

## Customer Impact

Customers wishing to use this latest firmware for their controllers can upgrade when as soon as convenient.

The firmware is available from Global SBS Support ([global-sbs.support@abb.com](mailto:global-sbs.support@abb.com)) or <https://cyloncommunity.com/> (North America)