ABB CYLON® TECHNICAL BULLETIN NO. 564
Issue Date: 25 February 2026

FBU Firmware 1.0.3

Products Affected: FBU-net, FBU-8R8

Summary

This firmware release is an incremental advance on the initial release `1.0.2`. It fixes issues found since release and improves the stability and functionality of the FBU system.

Detail

RESOLVED ISSUES

FBU-NET

SYSX-976 Updated FBU-Net UNET Monitor web page so that controllers not belonging to our network/site are no longer listed.

SYSX-977 Updated FBU-Net Dashboard web page to remove unecessary Service Time field.

FBU-8R8

SYSX-932 Updated FBU-8R8 Date Time web page to correctly display the controller's time & date, and to resolve a mismatch when the Time Zone was set to `Éire`.

SYSX-984 Fixed FBU-8R8 Real Time Module To correct the year output.

SYSX-987 Fixed FBU-8R8 operation with DI Module.

SYSX-988 Resolved FBU-8R8 issue where digital values could not be read properly when used with ASPECT.

SYSX-995 Addressed automatic closure of Datalog Manager during FBU-8R8 log reads and resolved intermittent communication fail/retry conditions.

Customer Impact

Customers should update their controllers to this latest firmware as soon as it is practical.

The firmware is available from Global SBS Support (global-sbs.support@abb.com)

©ABB 2026 All Rights Reserved.
Subject to change without notice
ABB.COM

B0398 rev 1