ABB

PCM600 version 2.9
Hotfix Rollup 20211119

Release of hotfix for Protection and Control IED Manager PCM600 version 2.9

Document Number: **1MRS228142**

Revision: A

Introduction

A hotfix package for Protection and Control IED Manager PCM600 version 2.9 has been released. We highly recommend the installation of this hotfix 20211119 when using PCM600 version 2.9.

Please refer next section for more details about improvements and corrections done in the hotfix.

Improvements and corrections

Improvements and corrections:

- Improved robustness on import of pcmp/pcmi, created in previous PCM600 versions

- Improved handling of Life Cycle Tool

This hotfix includes also the previously released hotfix for PCM600 version 2.9:

- PCM600 2.9 Hotfix 20181219.exe

- PCM600 2.9 Rollup 20190628.exe

- PCM600 2.9 Rollup 20190912.exe

Note: If the previously released hotfix package for PCM600 version 2.9 is already installed, then only the new hotfixes will be applied. If earlier hotfix for PCM600 version 2.9 has not been installed, then this hotfix package will apply all the updates.

The hotfix 20211119 for PCM600 version 2.9 is available via the PCM600 Update Manager and PCM600 Product Page. It contains the following file:

- PCM600 2.9 Hotfix 20211119.exe

We recommend the installation of this hotfix 20211119 when using PCM600 version 2.9.

For more information, please contact your local ABB representative.

ABB constantly examines both operational and new software to identify possible faults or product improvements, issuing hotfixes where appropriate. We apologize for any inconvenience the identified faults have caused.

Gaurav Srivastav

Global Product Manager

ABB

—

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.