ABB i-bus® EIB / KNX   **Software Information**

Product: **Interface to Radio Alarm System FAS9000**

Type: **FAS/EIB**

Current application program: **Interface Radio Alarm/1.1a**

==

Software-Information   to: Interface Radio Alarm/1.1a
                                  at: 10/2008

1.   Corrections

                                  • The order code was corrected. The wrong order code caused an error in
                                    the ETS when the Telephone Gateway TG/S 3.2 was imported also.

Software-Information   to: Interface Radio Alarm/1.1
                                  at: 06/2007

1.   Corrections

                                  • An error in the cyclic surveillance of bus detectors has been corrected.

                                  • The sending of text messages in case of unsetting of several areas at
                                    once has been corrected.