

SACE Emax 2

Blocco apertura della portella ad interruttore in inserito/test DLP - E2.2-E4.2-E6.2



Door opening lock with circuit-breaker in connected/test position DLP - E2.2-E4.2-E6.2


Verriegelung der Türöffnung bei Leistungsschalter in Betriebs-/Teststellung DLP - E2.2-E4.2-E6.2

Verrouillage ouverture du portillon avec disjoncteur en embroché/essai DLP - E2.2-E4.2-E6.2


Bloqueo apertura de la puerta con interruptor en posición insertado/prueba DLP - E2.2-E4.2-E6.2



E2.2-E4.2-E6.2






		A	B
E2.2	III	167 (6.57")	
	IV	257 (10.12")	167 (6.57")
E4.2	III	221 (8.70")	
	IV	347 (13.66")	221 (8.70")
E6.2	III	473 (18.62")	347 (13.66")
	IV	473 (18.62")	
	IV FS	599 (23.58")	473 (18.62")






5




6



7


LEFT SIDE







Estratto
Withdrawn
Entnommen
Débroché
Extraído

FIANCATA DX
RIGHT SIDE
RECHTE SEITE
FLANC D
LATERAL DER



Inserito
Connected
Betriebsstellung
Embroché
Insertado



For more information please contact:

ABB S.p.A.
ABB SACE Division
Via Pescaria, 5
24123 Bergamo - Italy
Phone: +39 035 395 111