Technical Bulletin
DALI Gateway Basic – Update Process Application Version 1.3

BUILDING AND HOME AUTOMATION SOLUTIONS

System:	i-bus® KNX	Product:	DG/S x.64.1.1, 6197/4x
Page:	1/1	Date:	28 July 2020

Important Note!!

After a successful download of the **application V 1.3**, it is absolutely necessary to reset the 230 V supply. The reason for this is that during a change of application and update of the DALI interface the DALI output itself is short-circuited and thus the lighting system cannot be influenced. "Green ON LED flashes".

By resetting the 230 V supply, this short circuit is cancelled again. If this reset is not performed, the DALI output stage may be destroyed. The DALI output stage is thermally destroyed after a certain time.

Here you can find more information about the update process of the application V1.3 and firmware V0.0.15.

PRODUCT TYPE	PRODUCT ID	WEBSITE
DG/S 1.64.1.1	2CDG110198R0011	Link
DG/S 2.64.1.1	2CDG110199R0011	Link
6197/45	2CKA006197A0043	Link
6197/46	2CKA006198A0043	Link