



BUILDING AND HOME AUTOMATION SOLUTIONS

# ABB-Welcome IP

## Release Note Firmware

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

<https://new.abb.com/low-voltage/products/building-automation/product-range/abb-welcome>

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved



BUILDING AND HOME AUTOMATION SOLUTIONS

# ABB-Welcome IP

## Release Note Firmware

Product name	Welcome IP Outdoor Station (IPpush button, IPkeypad, IPTouch 5) --- HGO05/HSM53 (View Website)
Product type	H81381T , H81381P, H81381K
Order code	2TMA130010X0001 2TMA130010X0002 2TMA130010X0003 2TMA130010X0009 2TMA130010W0021 2TMA130010W0025 2TMA130010W0029 2TMA130010W0013 2TMA130010W0033 2TMA130010W0037 2TMA130010X0019 2TMA130010X0020 2TMA130010X0021 2TMA130010X0027 2TMA130010X0043 2TMA130010X0044 2TMA130010W0023 2TMA130010W0027 2TMA130010W0031 2TMA130010W0017 2TMA130010W0035 2TMA130010W0039
Latest change	Firmware Update, September 2022

Current Status:

Product Type	Order Code	Website	Firmware
HGO05/HSM53	2TMA130010X0001 2TMA130010X0002 2TMA130010X0003 2TMA130010X0009 2TMA130010W0021 2TMA130010W0025 2TMA130010W0029 2TMA130010W0013 2TMA130010W0033 2TMA130010W0037 2TMA130010X0019 2TMA130010X0020 2TMA130010X0021 2TMA130010X0027 2TMA130010X0043 2TMA130010X0044 2TMA130010W0023 2TMA130010W0027 2TMA130010W0031 2TMA130010W0017 2TMA130010W0035 2TMA130010W0039	<a href="#">Link</a>	Firmware: 1.31

NOTE:

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

FIRMWARE

Product Type	Version	Release Date	Updates and Release Notes
HGO05/HSM53	V1.31	September 2022	New Features and UI improvements: <ul style="list-style-type: none"> <li>• Editable Font size for Residents list</li> <li>• New image for the 'Password/QRCode Unlock' icon on the main page</li> <li>• New order of personal details on the Resident List: the surname will be set before the the given name for all language</li> <li>• Automised call feature: a call will be automatically triggered when a specific contact on the Resident List is selected, after a 3 second pulsating count down</li> <li>• Newly added 'Stop Call' button: the button will allow to terminate the call during the 3 seconds count down when the automised call is triggered</li> </ul> Bugfixes: <ul style="list-style-type: none"> <li>• Various bugfixes</li> </ul>

HAUS- UND GEBÄUDEAUTOMATION

# ABB-Welcome IP

## Freigabemitteilung Firmware

Produktname	Welcome IP Outdoor Station (IPpush button, IPkeypad, IPTouch 5) --- HGO05/HSM53 ( <a href="#">View Website</a> )
Produkttyp	H81381T , H81381P, H81381K
Bestellnummer	2TMA130010X0001 2TMA130010X0002 2TMA130010X0003 2TMA130010X0009 2TMA130010W0021 2TMA130010W0025 2TMA130010W0029 2TMA130010W0013 2TMA130010W0033 2TMA130010W0037 2TMA130010X0019 2TMA130010X0020 2TMA130010X0021 2TMA130010X0027 2TMA130010X0043 2TMA130010X0044 2TMA130010W0023 2TMA130010W0027 2TMA130010W0031 2TMA130010W0017 2TMA130010W0035 2TMA130010W0039

Aktuelle Version

Firmware Update, September 2022

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	Firmware
HGO05/HSM53	2TMA130010X0001 2TMA130010X0002 2TMA130010X0003 2TMA130010X0009 2TMA130010W0021 2TMA130010W0025 2TMA130010W0029 2TMA130010W0013 2TMA130010W0033 2TMA130010W0037 2TMA130010X0019 2TMA130010X0020 2TMA130010X0021 2TMA130010X0027 2TMA130010X0043 2TMA130010X0044 2TMA130010W0023 2TMA130010W0027 2TMA130010W0031 2TMA130010W0017 2TMA130010W0035 2TMA130010W0039	<a href="#">Link</a>	Firmware: 1.31

**BEMERKUNG:**

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

**FIRMWARE**

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
HGO05/HSM53	V1.31	September 2022	<ul style="list-style-type: none"> <li>• Neue Funktionen und UI-Verbesserungen:               <ul style="list-style-type: none"> <li>○ Editierbare Schriftgröße für die Bewohnerliste</li> <li>○ Neues Bild für das Symbol "Passwort/QRCode entsperren" auf der Hauptseite</li> <li>○ Neue Reihenfolge der persönlichen Angaben in der Einwohnerliste: Der Nachname wird in allen Sprachen vor dem Vornamen angezeigt</li> <li>○ Automatische Anruffunktion: ein Anruf wird automatisch ausgelöst, wenn ein bestimmter Kontakt in der Bewohnerliste ausgewählt wird, nach einem pulsierenden Countdown von 3 Sekunden</li> <li>○ Neu hinzugefügte Schaltfläche "Anruf stoppen": Die Schaltfläche ermöglicht es, den Anruf während des 3-Sekunden-Countdowns zu beenden, wenn der automatische Anruf ausgelöst wird.</li> </ul> </li> <li>• Fehlerbehebungen:               <ul style="list-style-type: none"> <li>○ Verschiedene Fehlerkorrekturen</li> </ul> </li> </ul>