

INSTALLATION INSTRUCTIONS

# ReliaMod™ Modular Metering

## RBUSCAPDEEP



**HAZARDOUS VOLTAGE.  
WILL CAUSE SEVERE  
INJURY OR DEATH.**

Turn OFF power supplying this equipment before working inside.

Please read these instructions completely before installing or removing device. Improper installation could be hazardous to personnel and/or equipment.

**Kit Contains:**

Right Side Endcap	1
Gangway Nut	2

- Turn “OFF” power supplying the meter module.
- Install the right-side endcap on right end of the completed meter module ganging.
- Secure the endcap with the gangway nuts
- Torque nut to 26 in-lbf.



INSTRUCCIONES DE INSTALACIÓN

# ReliaMod™ Modular Metering

## RBUSCAPDEEP



**VOLTAJE PELIGROSO.  
PODRA CAUSAR MUERTE  
O LESIONES SERIAS.**

Desconecte la alimentación eléctrica de este equipo antes de realizar cualquier trabajo dentro o fuera de él.

Lea atentamente estas instrucciones antes de instalar o retirar el dispositivo. Una instalación incorrecta podría resultar peligrosa para el personal y/o el equipo.

**El kit contiene:**

Tapa lateral derecha	1
Tuerca de gangway	2

- Desconecta la alimentación del módulo de medidor.
- Instala la tapa lateral derecha en el extremo derecho del sistema completo de módulos de medidores.
- Fija la tapa con las tuercas.
- Aprieta las tuercas a 26 in-lbf.

