

ABB Drives			DRIVESPC 1.5 Operating Instruction			3AFE 00598614.DOC	
Dept.	Project	Status	Date	Author	Status	Revision	Page
	JALAPE		19.Oct 2009	RAKKOLAINEN JONI	DR	.2	1 / 1
	NO						

Problem: Following problem has been seen on some computers. If updating DriveSPC 1.4 with service pack to version 1.5 or installing new DriveSPC 1.5, launching v1.5 DriveSPC.exe or DriveSPC Pro.exe nothing happens.

Solution: New version of DriveSPC.exe is available for those problem cases. Please note there is separate exe versions for DriveSPC 1.5 and DriveSPC 1.5 Pro