

Content

1 Device - Revision Record - What is new?..... 1

1.1 Hardware ID: 0034..... 1

1.2 Software..... 1

1.3 Device..... 1

2 DTM (Device Type Manager) 1

2.1 Supported devices 1

2.2 DTM (driver) Version record - What is new? 1

2.3 Requirements..... 2

2.3.1 PC-Hardware, Operating system..... 2

2.3.2 Frame application / compatibility..... 2

2.4 Installation and configuration..... 2

2.4.1 Installation..... 2

2.4.2 Uninstall instructions..... 2

2.5 Update- / Upgrade instructions 2

2.6 Known problems and limitations..... 2

2.7 Getting help / further information..... 2

2.8 How to get the latest information & software? 2

2.9 Licensing the DTM..... 2

- *) DTM500 Bundle Supplement Info is available on the data medium \documentation or latest on www.abb.com/fieldbus. Enter here in the search field following No. "3KXD801500R3901".

1 Device - Revision Record - What is new?

1.1 Hardware ID: 0034

Released Revision	Released Date	Remarks
0255.00.03	Jan. 2010	First release

1.2 Software

Released Revision	Released Date	Remarks
2000.01.12	Jan. 2010	First release
2000.01.18	Dec. 2015	upgrade

1.3 Device

Released Revision	Released Date	Remarks
01	January 2010	First release

2 DTM (Device Type Manager)

2.1 Supported devices

- Combustion Gas Oxygen Analyzer Endura AZ20 HART with HW Version 0255.00.03., SW Version 2000.01.18 and Device Version 01 or higher.
- Combustion Gas Oxygen Analyzer Endura AZ25 HART with HW Version 0255.00.03., SW Version 2000.01.18 and Device Version 01 or higher.
- Combustion Gas Oxygen Analyzer Endura AZ30 HART with HW Version 0255.00.03, SW Version 2000.01.18 and Device Version 01 or higher.

2.2 DTM (driver) Version record - What is new?

Released Driver Version	Released Date	Released / Library Version	Remarks
05.00.00	Jun. 2010	≥ 05.01.00 / ≥ 05.00.15	- First release - Part of the DTM500 Bundle
05.00.01	Jun. 2011	≥ 05.03.00 / ≥ 05.00.17	- DTM Library update - Part of the DTM500 Bundle
05.00.02	Aug. 2012	≥ 05.04.00 / ≥ 05.00.18	- DTM500 Library Enhancements

05.00.03	May 2014	≥ 05.04.00 / ≥ 05.00.21	New DTM library for Compatibility with Win 8.1 and Win 2012 and 64 bits Operating systems Bugfixes: - Issue with DTM not appearing in catalog in certain Win 7 64 bit systems. - Error message on adding to network, in 64 bit systems when installation language is 'German'.
05.00.04	April 2017	≥ 05.05.00 / ≥ 05.00.22	New DTM library for "Observer role" in DCS
05.00.05	March 2019	≥ 05.05.00 / ≥ 05.00.22	DTM for DCS

→ latest info (download) [*device type dependent*] - Driver description
- Software [*driver type dependent*]

2.9 Licensing the DTM

See DTM500 Bundle Supplement Info*)

- The device DTM supports the standard FDT 1.2 / 1.2.1.

2.3 Requirements

2.3.1 PC-Hardware, Operating system

See DTM500 Bundle Supplement Info*)

2.3.2 Frame application / compatibility

See DTM500 Bundle Supplement Info*)

2.4 Installation and configuration

2.4.1 Installation

See DTM500 Bundle Supplement Info*)

2.4.2 Uninstall instructions

See DTM500 Bundle Supplement Info*)

2.5 Update- / Upgrade instructions

See DTM500 Bundle Supplement Info*)

2.6 Known problems and limitations

Additionally to the common hints in the DTM500 Bundle Supplement Info*) attached the device driver specific hints.

Installation of version 05.00.04

UNINSTALL 05.00.03 (IF ALREADY INSTALLED) BEFORE INSTALLING 05.00.04.

In case of upgrade attempt, DTM will fail to install properly. To recover from this, refer to "!\Instructions for upgrade.txt" in installation Zip-File

2.7 Getting help / further information

- Press 'F1' for DTM online help.
- Help concerning the integration of the DTM in the FDT frame application can be found in the respective documentation of the frame application.

2.8 How to get the latest information & software?

The latest device driver Supplement Info & software (driver) is available on www.abb.com/fieldbus:

→ latest information [*field device protocol dependent*]

**ABB has Sales & Customer Support
expertise in over 100 countries worldwide.**

<http://www.abb.com/instrumentation>

The Company's policy is one of continuous product improvement and the right is reserved to modify the information contained herein without notice.

Printed in the Fed. Rep. of Germany (03.2019)

© ABB 2019

3KXA722201R3901 Rev. G



Germany

ABB Automation Products GmbH
Borsigstr. 2
63755 Alzenau

Tel: +49 (0)551 905-534
Fax: +49 (0)551 905-555

vertrieb.instrumentation@de.abb.com

USA

ABB Inc.
125 E. County Line Road
Warminster, PA
18974-4995

Tel: +1 (0)215 674 6000
Fax: +1 (0)215 674 7183

instrumentation@us.abb.com

Italy

ABB S.p.A.
Via Statale 113
22016 Lenno (CO)

Tel: +39 0344 58111
Fax: +39 0344 56278

abb.instrumentation@it.abb.com

UK

ABB Limited
Oldends Lane
Stonehouse
Gloucestershire GL10 3TA

Tel: +44 (0)1453 826 661
Fax: +44 (0)1453 829 671

instrumentation@gb.abb.com

P.R. China

ABB Engineering (Shanghai) Ltd.
32 Industrial Area
Kangqiao Town, Nanhui District
Shanghai, 201319

Tel: +86 (0) 21 6105 6666
Fax: +86 (0) 21 6105 6677

china.instrumentation@cn.abb.com