

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L121190-33751-91600002-3
Report Reference E121190-20000619
Date 24-May-2023

Issued to: ABB Stotz-Kontakt GmbH
Eppelheimer Str 82
Heidelberg, Baden-Wurttemberg 69123
Germany

This is to certify that representative samples of NLRV7 - Motor Controllers, Manual Certified for Canada
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: CSA C22.2 No. 60947-1, 2nd Ed., Issue Date: 2013-07-01,
CSA C22.2 NO. 60947-4-1, 2nd Ed., Issue Date: 2014-04-04, Revised 2018-05

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L121190-33751-91600002-3
Report Reference E121190-20000619
Date 24-May-2023

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
Accessories, Feeder Block, DBM32	Motor Controllers - Manual
Accessories, Feeder Block, DBM35	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, DM32, followed by -210, -240, -207, -208, may be followed by S	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS1, followed by -2, -3, -4, -5 or -6 followed by -0 or -1 -2 followed by -65, -100.	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS1 followed by, -2, -3, -4, or -5, followed by -0 or -1 followed by -65, followed by K.	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS2, followed by -2, -3, -4, or -5 followed by -0, -1 or -2 followed by -125.	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS3, followed by -2, -3, -4, -5 or -6 followed by -0, -1 or -2.	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS3-2-2	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS3-4-2	Motor Controllers - Manual
Accessories, Feeder Block, S1-M1-25	Motor Controllers - Manual
Accessories, Feeder Block, S1-M2-25	Motor Controllers - Manual
Accessories, Feeder Block, S1-M3-25	Motor Controllers - Manual
Accessories, Feeder Block, S1-M3-35	Motor Controllers - Manual
Accessories, Feeder Block, S2-M3-50	Motor Controllers - Manual
Accessories, Feeder Block, S3-M1	Motor Controllers - Manual
Accessories, Feeder Block, S3-M2	Motor Controllers - Manual
Accessories, Feeder Block, S3-M3	Motor Controllers - Manual



Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L121190-33721-91600002-3
Report Reference E121190-20000619
Date 24-May-2023

Issued to: ABB Stotz-Kontakt GmbH
Eppelheimer Str 82
Heidelberg, Baden-Wurttemberg 69123
Germany

This is to certify that representative samples of NLRV - Motor Controllers, Manual
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 60947-4-1, 3rd Ed., Issue Date: 2014-04-04, Revision Date: 2017-10-17, UL 60947-1, 5th Ed., Issue Date: 2013-7-31, Revision Date: 2019-5-6

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L121190-33721-91600002-3
Report Reference E121190-20000619
Date 24-May-2023

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
Accessories, Feeder Block, DBM32	Motor Controllers - Manual
Accessories, Feeder Block, DBM35	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, DM32, followed by -210, -240, -207, -208, may be followed by S	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS1, followed by -2, -3, -4, -5 or -6 followed by -0 or -1 -2 followed by -65, -100.	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS1 followed by, -2, -3, -4, or -5, followed by -0 or -1 followed by -65, followed by K.	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS2, followed by -2, -3, -4, or -5 followed by -0, -1 or -2 followed by -125.	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS3, followed by -2, -3, -4, -5 or -6 followed by -0, -1 or -2.	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS3-2-2	Motor Controllers - Manual
Accessories, Feeder Bus Bar Assembly, PS3-4-2	Motor Controllers - Manual
Accessories, Feeder Block, S1-M1-25	Motor Controllers - Manual
Accessories, Feeder Block, S1-M2-25	Motor Controllers - Manual
Accessories, Feeder Block, S1-M3-25	Motor Controllers - Manual
Accessories, Feeder Block, S1-M3-35	Motor Controllers - Manual
Accessories, Feeder Block, S2-M3-50	Motor Controllers - Manual
Accessories, Feeder Block, S3-M1	Motor Controllers - Manual
Accessories, Feeder Block, S3-M2	Motor Controllers - Manual
Accessories, Feeder Block, S3-M3	Motor Controllers - Manual



Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>