

CB Line Firmware 9.3.7

Products Affected: CBT-3T6-5R, CBT-4T4-2U1R, CBV-2U4-3T, CBV-2U4-3T-N, CBX-8R8, CBX-8R8-H

Summary

This is an incremental update that fixes reported issues and adds enhancements.

Features

42790 – ENHANCEMENT: HOLD OUTPUTS DURING STRATEGY DOWNLOAD

Added support for holding output values during a strategy download to prevent unintended state changes.

- The controller freezes output values at the start of the strategy download.
- When the download completes, the Hold Outputs state is cleared.
- Any configuration or strategy changes will still update the relevant outputs as expected.

If communication is lost during a download, Hold Outputs will **automatically clear after 60 seconds**.

USER FEEDBACK:

The Override LED provides a visual indication of the **Hold Outputs** activation, using the same pattern as an override indication.

43899 – FIXED ISSUE

Updating/writing **Weekly Schedule days** times via **BACnet** has been restored.

Customer Impact

Customers should upgrade as soon as is convenient.

The firmware can be download from our support web sites:

- North America <https://abbcommunity.com/>
- Europe/ROW <http://support.cylon.com/>