



BUILDING AND HOME AUTOMATION SOLUTIONS

ABB-Welcome IP

Release Note Firmware

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

<https://new.abb.com/low-voltage/products/building-automation/product-range/abb-welcome>

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

ABB-Welcome IP

Release Note Firmware

Product name Guard unit
Product type H8303
Order code 2TMA130160W0018
Latest change Firmware Update, September 2022

Current Status:

Product Type	Order Code	Website	Firmware
H8303	2TMA130160W0018	Link	Firmware: 1.40

NOTE:

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

FIRMWARE

Product Type	Version	Release Date	Updates and Release Notes
H8303	V1.40	September 2022	<ul style="list-style-type: none">• New features:<ul style="list-style-type: none">○ Modification of Summer Hours functions.• Bugfixes:<ul style="list-style-type: none">○ Various bugfixes

HAUS- UND GEBÄUDEAUTOMATION

ABB-Welcome IP

Freigabemitteilung Firmware

Produktname	Guard Unit
Produkttyp	H8303
Bestellnummer	2TMA130160W0018
Aktuelle Version	Firmware Update, September 2022

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	Firmware
H8303	2TMA130160W0018	Link	Firmware: 1.40

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

FIRMWARE

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
H8303	V1.40	September 2022	<ul style="list-style-type: none">• Neue Funktionen:<ul style="list-style-type: none">o Modifikation der Sommerzeit-Funktionen.• Fehlerbehebungen:<ul style="list-style-type: none">o Verschiedene Bugfixes