

<b>ABB</b>	Lifecycle Status Statement			DOCLCM05MA001
Issued by	Date	Language	Revision	Page
ABB ATG/SE, Sales Support	13.12.2005	en	B	1 (1)
Creator name	Karl-Heinz Ahl		Distribution	Public

## 05 MA.. Servo Drives (AXODYN®)

### 1. CURRENT LIFECYCLE STATUS

The 05 MA.. drive product has been in the obsolete phase since the beginning of 2006 according to the ABB lifecycle model outlined below.

### 2. SUPPORT AVAILABILITY FOR 05 MA..

During the obsolete phase ABB can not guarantee availability of product support within reasonable cost or technically:

- Sale of 05 MA.. parts is limited to available inventory.
- Sale of 05 MA.. repair services is limited to component availability.

### 3. RECOMMENDED ACTION

It is recommended that 05 MA.. drive product customers migrate to replacement products.


For a suitable replacement solution please contact us.

[Use the Link below](#) and give us Information about the existing installation, as much as possible.

### 4. FURTHER INFORMATION

For further information please contact [mailto:Parts-Repair-LPH DEPID/DE/ABB@ABB\\_DE01](mailto:Parts-Repair-LPH DEPID/DE/ABB@ABB_DE01)

### 5. ABB LIFECYCLE MODEL



Specifications subject to change without notice.