



For more information about the connection of the unlock signal, see document 2TLC01000410201 on abb.com/jokabsafety

			Datum	2018-12-19	ABB	ABB Jokab Safety	GKey_Tina3PS_2TLC010023T0008	= GKey
			Redigerare	SEHAHAL5	New products			+
			Kontrollerad					
Ändring	Datum	Namn	Ursprung		Ersättning for	Ersatt av		
								Blad 6
							HHg_New	Blad 12 / 23