

INSTALLATION INSTRUCTIONS

# ReliaMod™ Modular Metering

## RBUSCAPFLAT



**HAZARDOUS VOLTAGE.  
WILL CAUSE SEVERE  
INJURY OR DEATH.**

Turn OFF power supplying this equipment before working inside.

Please read these instructions completely before installing or removing device. Improper installation could be hazardous to personnel and/or equipment.

**Kit Contains:**

Left Side Endcap	1
Gangway Nut	2



- Turn “OFF” power supplying the meter module.
- Install the left-side endcap on left end of the completed meter module ganging.
- Secure the endcap with the gangway nuts
- Torque nut to 26 in-lbf.

INSTRUCCIONES DE INSTALACIÓN

# ReliaMod™ Modular Metering

## RBUSCAPFLAT



**VOLTAJE PELIGROSO.  
PODRA CAUSAR MUERTE  
O LESIONES SERIAS.**

Desconecte la alimentación eléctrica de este equipo antes de realizar cualquier trabajo dentro o fuera de él.

Lea atentamente estas instrucciones antes de instalar o retirar el dispositivo. Una instalación incorrecta podría resultar peligrosa para el personal y/o el equipo.

**El kit contiene:**

Tapa lateral izquierda	1
Tuerca de gangway	2



- Desconecta la alimentación del módulo de medidor.
- Instala la tapa lateral izquierda en el extremo izquierdo del Sistema completo de módulos de medidores.
- Fija la tapa con las tuercas.
- Apriete las tuercas a 26 in-lbf.