

# Pilot Devices

## Emergency stops - Design update



Pilot devices

### New design due to changes in standards

According to the new regulations in IEC 60947-5-5 emergency stops are no longer allowed to have markings or labels in white. When it is necessary to identify the direction of the unlatching of the actuator, this identification should have the same or nearly the same color as the actuator.

Please have a look at the figure to gain a better understanding of the how the safety of machinery standard ISO 13850 is connected to IEC 60947-5-5.

### Consequences of the new design

Because of these changes in regulations we have changed the design of both compact and modular range, illuminated and non illuminated, for both twist and pull release emergency stops during 2016. This changes that was implemented on the 1st of April 2016 will not affect the article numbers.

### An overview of the standards applicable to emergency stops:

