



RELEASE NOTE – SEP 15, 2023 2NGA1834

# PCM600 version 2.12

## Hotfix 20230915

Release of hotfix for Protection and Control IED Manager PCM600 version 2.12



ABB Oy

Distributed Solutions

P.O. Box 699

FI-65101 Vaasa, Finland

Phone: +358 10 22 11

[go.abb/digitalsubstations](https://go.abb/digitalsubstations)

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2023 ABB

All rights reserved



## Introduction

A hotfix package for Protection and Control IED Manager PCM600 version 2.12 has been released. We strongly recommend the installation of this hotfix 20230915 when using PCM600 version 2.12.

Please refer next section for more details about improvements and corrections done in the hotfix.

---

ABB Oy

Distributed Solutions

P.O. Box 699

FI-65101 Vaasa, Finland

Phone: +358 10 22 11

[go.abb/digitalsubstations](https://go.abb/digitalsubstations)

---

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

---

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2023 ABB

All rights reserved

## Improvements and corrections



### Improvements and corrections:

- Support for common APPID for Goose Control Blocks.
- Improved robustness with Update Manager when it is connected to alternate source.
- Improved robustness with Easy Goose Engineering in Application Configuration.
- Improved robustness of Command Line Interface functionalities.
- Enabled retaining R-GOOSE configuration in SCL file export/import and read/write.

---

ABB Oy

Distributed Solutions

P.O. Box 699

FI-65101 Vaasa, Finland

Phone: +358 10 22 11

[go.abb/digitalsubstations](https://go.abb/digitalsubstations)

---

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

---

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2023 ABB

All rights reserved



This hotfix includes also the previously released hotfix for PCM600 version 2.12:

- PCM600 2.12 Hotfix 20230213.exe

The hotfix **20230915** for PCM600 version 2.12 is available via the PCM600 Update Manager and PCM600 Product Page. It contains the following file:

- PCM600 2.12 Hotfix 20230915.exe

We recommend the installation of this hotfix **20230915** when using PCM600 version 2.12.

For more information, please contact your local ABB representative.

ABB constantly examines both operational and new software to identify possible faults or product improvements, issuing hotfixes where appropriate. We apologize for any inconvenience the identified faults have caused.

## Known limitations

- During installation of PCM600 2.12 Hotfix 20230915, PCM600 projects created with PCM600 2.11 version are converted to PCM600 2.12. Depending on number of PCM600 2.11 projects, the conversion process might take a few minutes to complete.
- Avoid using F3 key when working with data grid in PCM600 version 2.12 and hotfixes.

Gaurav Srivastav

Global Product Manager

ABB

---

ABB Oy  
Distributed Solutions  
P.O. Box 699  
FI-65101 Vaasa, Finland  
Phone: +358 10 22 11  
[go.abb/digitalsubstations](https://go.abb/digitalsubstations)

---

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

---

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2023 ABB

All rights reserved