

TECHNICAL NOTE

Tina in combination with Focus I/II

Description

It has come to ABB's attention that when using the combination of some of the signal converter Tina variants with the obsolete light guard Focus I/Focus II, there is a very unlikely risk that the light guards will not function as intended.

N.B. This issue does not affect the current Orion light guard family in combination with any Tina product. It is only affecting the Tina and Focus combinations.

What to do

Please contact ABB if you are using any of the products listed below in combination with a Focus I or Focus II light guard. No action is needed when using Orion light guards.

Affected Tina variants

Part name	Brand	Part number
Tina 10A	ABB	2TLA020054R1200
	ABB Jokab Safety	2TLJ020054R1200
	Jokab Safety	20-054-12
Tina 10B	ABB	2TLA020054R1300
	ABB Jokab Safety	2TLJ020054R1300
	Jokab Safety	20-054-13
Tina 10C	ABB	2TLA020054R1600
	ABB Jokab Safety	2TLJ020054R1600
	Jokab Safety	20-054-16
FMC-1 Tina	ABB	2TLA022045R0000
	ABB Jokab Safety	2TLJ022045R0000
	Jokab Safety	22-045-00
FMC-1A Tina	ABB Jokab Safety	2TLJ022047R0000
	Jokab Safety	22-047-00
FMC-2 Tina	ABB	2TLA022046R0000
	ABB Jokab Safety	2TLJ022046R0000
	Jokab Safety	22-046-00