



RELEASE NOTE – MAR 07, 2024

PCM600 version 2.12

Hotfix 20240307

Release of hotfix for Protection and Control IED Manager PCM600 version 2.12



ABB Oy

Distribution Solutions

P.O. Box 699

FI-65101 Vaasa, Finland

Phone: +358 10 22 11

go.abb/digitalsubstations

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2024 ABB

All rights reserved



Introduction

A hotfix package for Protection and Control IED Manager PCM600 version 2.12 has been released. We strongly recommend the installation of this hotfix 20240307 when using PCM600 version 2.12.

Please refer next section for more details about improvements and corrections done in the hotfix.

Improvements and corrections



ABB Oy

Distribution Solutions

P.O. Box 699

FI-65101 Vaasa, Finland

Phone: +358 10 22 11

go.abb/digitalsubstations

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2024 ABB

All rights reserved



Improvements and corrections:

- Improved robustness in configuration migration to retain horizontal communication information.
- Improved robustness with symbol caption in Graphical Display Editor.
- Improved robustness in Application Configuration where in some cases save button used to get enabled due to presence of inverted signal in Application Configuration.
- Improved robustness with SCL files import-export operations.
- A *link** to ABB's technical documentation portal introduced in IED context menu.

** Certain functionalities are available only for supported products.*

This hotfix includes also the previously released hotfixes for PCM600 version 2.12:

- PCM600 2.12 Hotfix 20230915.exe
- PCM600 2.12 Hotfix 20230213.exe

The hotfix 20240307 for PCM600 version 2.12 is available via the PCM600 Update Manager and PCM600 Product Page. It contains the following file:

- PCM600 2.12 Hotfix 20240307.exe

We recommend the installation of this hotfix **20240307** when using PCM600 version 2.12.

For more information, please contact your local ABB representative.

ABB constantly examines both operational and new software to identify possible faults or product improvements, issuing hotfixes where appropriate. We apologize for any inconvenience the identified faults have caused.

—

ABB Oy
Distribution Solutions
P.O. Box 699
FI-65101 Vaasa, Finland
Phone: +358 10 22 11

go.abb/digitalsubstations

—

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

—

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2024 ABB

All rights reserved



Known limitations

- During installation of PCM600 2.12 Hotfix 20240307, PCM600 projects created with PCM600 2.11 version are converted to PCM600 2.12. Depending on number of PCM600 2.11 projects, the conversion process might take a few minutes to complete.
- Avoid using F3 key when working with data grid in PCM600 version 2.12 and hotfixes.

Gaurav Srivastav

Global Product Manager

ABB

—

ABB Oy

Distribution Solutions

P.O. Box 699

FI-65101 Vaasa, Finland

Phone: +358 10 22 11

go.abb/digitalsubstations

—

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

—

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2024 ABB

All rights reserved