

<b>ABB</b>	Lifecycle Status Statement			DOCLCMSDS1001
Issued by	Date	Language	Revision	Page
ABB ATG/SE, Sales Support	22.02.2007	en	B	1 (1)
Creator name	Karl-Heinz Ahl		Distribution	Public

## SDS100 Servo Inverters

### 1. CURRENT LIFECYCLE STATUS

The SDS 10. drive product has been in the obsolete phase since the beginning of 2007 according to the ABB Drives lifecycle model outlined below.

### 2. SUPPORT AVAILABILITY FOR SDS 10.

During the obsolete phase ABB can not guarantee availability of product support within reasonable cost or technically:

- Sale of SDS10. parts is limited to available inventory.
- Sale of SDS10. repair services is limited to component availability.

### 3. RECOMMENDED ACTION

It is recommended that SDS10. drive product customers migrate to replacement products.

For a suitable replacement solution please contact us.

[Use the Link below](#) and give us Information about the existing installation, as much as possible.

### 4. FURTHER INFORMATION

For further information, please contact ABB by [mailto:Parts-Repair-LPH\\_DEPID/DE/ABB@ABB\\_DE01](mailto:Parts-Repair-LPH_DEPID/DE/ABB@ABB_DE01)

### 5. ABB LIFECYCLE MODEL

