

# Important software update Embedded software withdrawn

1 FEBRUARY 2023 | 2108346TB-TB224

## Description

The embedded software versions described in [Table 1](#) below have issues with the Plunger Application and have been withdrawn by ABB. Their use must be discontinued.

## Is your product impacted?

Systems with the following software versions are impacted:

Table 1: Withdrawn software versions per product

Product	Withdrawn package (OS+Flash)	Withdrawn package (Flash-only)
XFC <sup>G5</sup>	2105808-015	2105805-018
XRC <sup>G5</sup>	2105880-015	2105864-018
RMC-Standard	2105454-042	2105457-039
RMC-LI TE	2106260-013	2106229-013
UDC	2106532-005	Not applicable
XFC <sup>G4</sup> 6200/6201EX (SU)	Not applicable	2104158-050
XFC <sup>G4</sup> 6200/6201EX (US)	Not applicable	2104159-050
XIO	2106200-010	2106198-010

## Resolution

ABB recommends that you stop using any of the versions listed in [Table 1](#) above. If they have been installed on your systems, remove them, and use the versions listed in [Table 2](#) in the interim.

Planned versions to address the problem will be available on as soon as possible. ABB recommends systems to be upgraded to these versions when they become available.

Install packages are available at each product page on the ABB website ([www.abb.com/upstream](http://www.abb.com/upstream)) or at the [ABB library download center](#).

Table 2: Recommended earlier released software versions

Product	(OS+Flash)	Flash-only
XFC <sup>G5</sup>	2105808-014	2105805-017
XRC <sup>G5</sup>	2105880-014	2105864-017
RMC-Standard	2105454-041	2105457-038
RMC-LI TE	2106260-012	2106229-012

Product	(OS+Flash)	Flash-only
UDC	2106532-004	Not applicable
XFC <sup>G4</sup> 6200/6201EX (SU)	Not applicable	2104158-049
XFC <sup>G4</sup> 6200/6201EX (US)	Not applicable	2104159-049
XIO	2106200-009	2106198-010

—  
ABB Inc.

Measurement & Analytics

Quotes: [US-IAMA.inquiry@us.abb.com](mailto:US-IAMA.inquiry@us.abb.com)

Orders: [US-IAMA.order@us.abb.com](mailto:US-IAMA.order@us.abb.com)

Training: [US-IAMA.training@us.abb.com](mailto:US-IAMA.training@us.abb.com)

Support: [upstream.support@us.abb.com](mailto:upstream.support@us.abb.com)

+1 800 442 3097 (opt. 2)

Additional free publications are available for download at:

[www.abb.com/upstream](http://www.abb.com/upstream)

Main Office - Bartlesville  
7051 Industrial Blvd  
Bartlesville, OK 74006  
Ph: +1 918 338 4888

Texas Office - Houston  
3700 W. Sam Houston  
Parkway S., Suite 600  
Houston, TX 77042  
Ph: +1 713 587 8000

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents - in whole or in parts – is forbidden without prior written consent of ABB.

2108346TB-TB224

Copyright© 2023 ABB all rights reserved