

CERTIFICATE OF COMPLIANCE

Certificate Number E244328
Report Reference E244328-20080923
Issue Date 2022-JUNE-30

Issued to: ABB Stotz-Kontakt GmbH
Hauptstrasse 14-16
Hornberg, 78132 Germany

**This certificate confirms that
representative samples of**

RELAY SOCKETS AND ASSEMBLIES - COMPONENT
See next page for models.

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 508 & CSA C22.2 NO. 14, Industrial Control Equipment.
Additional Information: See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product. |



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E244328
Report Reference E244328-20080923
Issue Date 2022-JUNE-30

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Relay socket and assemblies, models:

CR-PSS, CR-PLS, CR-M2SS, CR-M2LS, CR-M2SF, CR-M3SS, CR-M3LS, CR-M4SS, CR-M4LS, CR-M4SF, CR-U2SM, CR-U3SM

Plug-in modules, models:

CR-P/M 22, CR-P/M 42, CR-P/M 42V, CR-P/M 42B, CR-P/M 42BV, CR-P/M 42C, CR-P/M 42CV, CR-P/M 52B, CR-P/M 52C, CR-P/M 52D, CR-P/M 62, CR-P/M 92, CR-P/M 62V, CR-P/M 92V, CR-P/M 62E, CR-P/M 62EV, CR-P/M 62C, CR-P/M 92C, CR-P/M 62CV, CR-P/M 92CV, CR-P/M 62D, CR-P/M 62DV, CR-P/M 72, CR-P/M 72A, CR-P/M 82, CR-U 21, CR-U 41, CR-U 41V, CR-U 41B, CR-U 41BV, CR-U 41C, CR-U 41CV, CR-U 51B, CR-U 51C, CR-U 51D, CR-U 61, CR-U 91, CR-U 61V, CR-U 91V, CR-U 61E, CR-U 61EV, CR-U 61C, CR-U 91C, CR-U 61CV, CR-U 91CV, CR-U 61D, CR-U 61DV, CR-U 71, CR-U 71A, CR-U 81, CR-M2LSH, CR-M3LSH

Relay sockets and assemblies, models:

CR-U2S 1SVR405670R0010, CR-U3S 1SVR405660R0010, CR-S006/024VDC1SS, CR-S012/024VADC1SS, CR-S048/060VADC1SS, CR-S110/125VADC1SS, CR-S220/240VADC1SS, CR-M2SFB, CR-M4SFB, CR-S012/024VADC1SZ, CR-S048/060VADC1SZ, CR-S110/125VADC1SZ, CR-S220/240VADC1SZ, CR-S006/024VDC1SZ, CR-PLC, CR-M4LC, CR-PLP, CR-M2LP, CR-M4LP



Bruce Mahrenholz, Conformity Assessment Director

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <http://ul.com/aboutul/locations/>

