



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DE/BVS/QAR14.0004/11	Page 1 of 2
QAR Free Ref. No.:	ZQS/E379/23	Status: Issued
Details of change:	No details to be mentioned regarding production of explosion protected equipment.	Date of issue: 2023-03-24
Site(s) audited:	ABB STOTZ-KONTAKT GMBH Eppelheimer Strasse 82 69123 Heidelberg Germany ABB STOTZ-KONTAKT GmbH Hauptstrasse 14-16 78132 Hornberg Germany ABB Bulgaria EOOD 1, Varna Str. 2850 Petrich Bulgaria ABB Xinhui Low Voltage Switchgear Company Limited Jinguzhou Industrial Development Zone Xinhui District Jiangmen City, Guangdong Provinve 529100 China	Valid until: 2026-03-26 Audit date: 2023-03-09
Issuing ExCB:	BVS - DEKRA Testing and Certification GmbH	
Manufacturer:	ABB STOTZ-KONTAKT GMBH Eppelheimer Strasse 82 69123 Heidelberg	
Location of Manufacturer:	Germany	
Product information:	Motor protection devices as well time relays and power supplies intended to be installed on a DIN rail	
Protection concept:	Increased safety "e" Flameproof enclosure "d" Pressurized enclosures "p" Protection by enclosure "t" Type of protection "n"	
Related QARs:	<div>DE/BVS/QAR14.0004/00 DE/BVS/QAR14.0004/03 DE/BVS/QAR14.0004/06 DE/BVS/QAR14.0004/09</div> <div>DE/BVS/QAR14.0004/01 DE/BVS/QAR14.0004/04 DE/BVS/QAR14.0004/07 DE/BVS/QAR14.0004/10</div> <div>DE/BVS/QAR14.0004/02 DE/BVS/QAR14.0004/05 DE/BVS/QAR14.0004/08</div>	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:	<div>IECEx BVS 17.0016 issue: 0 IECEx BVS 17.0070 issue: 0 IECEx BVS 17.0072 issue: 1 IECEx ULD 17.0031X issue: 0 IECEx ULD 17.0031X issue: 3</div> <div>IECEx BVS 17.0066 issue: 0 IECEx BVS 17.0070 issue: 1 IECEx BVS 17.0073 issue: 0 IECEx ULD 17.0031X issue: 1 IECEx ULD 22.0013X issue: 0</div> <div>IECEx BVS 17.0068 issue: 0 IECEx BVS 17.0072 issue: 0 IECEx BVS 17.0074 issue: 0 IECEx ULD 17.0031X issue: 2</div>	



IECEX Quality Assessment Report Summary

QAR Ref. No.: **DE/BVS/QAR14.0004/11**

Page 2 of 2

Comments: