

HOTFIX ROLLUP RELEASE NOTE

PCM600 version 2.8

Hotfix rollup 20180111



Dear PCM600 User

A hotfix rollup package for Protection and Control IED Manager PCM600 version 2.8 has been released. The hotfix rollup 20180111 for PCM600 version 2.8 includes improvements and corrections for the following issues:

- Better handling of IEC 61850, in the receiver side only intended GOOSE Control Blocks are processed.
- Corrected graphical representation of inverted signal in Application Configuration.

This hotfix rollup includes also the previously released hotfix/rollups for PCM600 version 2.8:

PCM600 2.8 Rollup 20171027.exe
PCM600 2.8 Rollup 20170621.exe
PCM600 2.8 Hotfix 20170320.exe

Note: If the previously released hotfix\rollups package for PCM600 version 2.8 is already installed, then only the new hotfixes\rollups will be applied. If earlier hotfix\rollups for PCM600 version 2.8 has not been installed, then this rollup package will apply all the updates.

The hotfix rollup 20180111 for PCM600 version 2.8 is available via the PCM600 Update Manager and ABB software library. It contains the following file:

- PCM600 2.8 Rollup 20180111.exe

We recommend the installation of this hotfix rollup 20180111 when using PCM600 version 2.8.



For more information, please contact your local ABB representative.

ABB constantly examines both operational and new software to identify possible faults or product improvements, issuing hotfixes where appropriate. We apologize for any inconvenience the identified faults have caused.

Kind regards,

Raghuvendra Singh

Global Product Manager

ABB

Henry Niveri

Product Manager

ABB