

HOTFIX RELEASE NOTE

PCM600 2.6

Hotfix Rollup 20150923



Dear PCM600 User

A new hotfix rollup package for Protection and Control IED Manager PCM600 2.6 has been released.

The hotfix 20150923 for PCM600 2.6 is solving the following issues:

- A potential error in IED user management functionality is causing PCM600 to write faulty IED user passwords to the relay. Due to that, the passwords which are stored on the IED do not match a particular user's given password. The consequence of this bug is that a user cannot login to the relay any more.
- A problem in Application configuration tool is causing duplicate inverter instances when importing application configuration template files.

This hotfix rollup includes also the previously released rollup/hotfixes for PCM600 2.6:


- Hotfix rollup 20150626
- Hotfix rollup 20150511
- Hotfix rollup 20140929
- Hotfix rollup 20140626
- Hotfix 20140130

Note: If the previously released hotfix rollup packages for PCM600 2.6 are already installed, then only the new hotfixes will be applied. If earlier released rollup/hotfixes for PCM600 2.6 has not been installed, then this rollup package will apply all the updates.

The hotfix 20150923 for PCM600 2.6 is available via the PCM600 Update Manager. It contains the following file:

- PCM600 2.6 Rollup 20150923 .exe

We recommend the installation of this Rollup 20150923 when using PCM600 2.6.



For more information, please contact your local ABB representative.

ABB constantly examines both operational and new software to identify possible faults or product improvements, issuing hotfixes where appropriate. We apologize for any inconvenience the identified faults have caused.

Kind regards,

Beat Schuetz
Global Product Manager
ABB Substation
Automation products

Henry Niveri
Product Manager
ABB Distribution
Automation

ABB Oy
Medium Voltage Products,
Distribution Automation
P.O. Box 699
FI-65101 VAASA, Finland
Phone +358 10 22 11
Fax +358 10 22 41599
<http://abb.com/mediumvoltage>

ABB AB
Grid Automation Products
SE-721 59 Vasteras, Sweden
Phone +46 (0) 21 32 50 00
Fax +46 (0) 21 14 69 18
<http://abb.com/substation-automation>

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB. Copyright © 2015 ABB
All rights reserved