


NOTES:

1. **WARNING**  
Using a non-factory RS232 data cable between UC12 unit may result in damage and may void system warranty.
2. All installations in hazardous locations must comply with requirements of Certification Drawing 2017275-CD.
3. Dial-Up Modem Configuration Shown. When using dial-up dual port modem, power to be connected to P1-9.

4. Software Scheduler Required

Plug in modules with smooth side of the module on the left which puts pin 1 on the bottom.



REF: 2100656-WI

<b>ABB</b>	TOTALFLOW Products	ACTION	DOC TYPE	TITLE	DWG NO.	REV	SHEET
		D19344	UD	XRC 6490\6790\6890 COMM 2 (2100355 BD) TO UC12 W/EXT SWITCHED POWER (RS-232)	2102211	AB	1 OF 1