



BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

Video indoor station 4.3 WiFi

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

ABB Xiamen Smart Technology Co., Ltd.
No.7 Fangshan South Road,
Xiang An, Xiamen, Fujian, P.R.China
Phone:
Email:
<https://new.abb.com/low-voltage/products/building-automation/product-range/abb-welcome>

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

Video indoor station 4.3 WiFi

Product name Video indoor station 4.3, WiFi
Product type M22401-W, M22403-W, M22401-W-03, M22401-W-04
Order code 2TMA220050W0022, 2TMA220050W0024, 2TMA220050W0026, 2TMA200051W0001
Latest change Firmware Update, 08/12/2021

Current Status:

Product Type	Order Code	Website	Firmware
M22401-W	2TMA220050W0022	Link	V1.12 update via Welcome App
M22403-W	2TMA220050W0024	Link	
M22401-W-03	2TMA220050W0026	Link	
M22401-W-04	2TMA200051W0001	Link	

NOTE:

If your device is connected to the Internet and the Welcome app is paired, then you will shortly receive a request for an automatic software update

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

FIRMWARE

Product Type	Version	Release Date	Updates and Release Notes
M22401-W M22403-W M22401-W-03 M22401-W-04	1.12	08/12/2021	<ul style="list-style-type: none"> • During the Paring process the Welcome App send the myBuildings Portal credentials automatically to the Wifi Indoor Station • Based on your smartphone country selection the Wifi Indoor Station will enable additionally the channels 12 and 13 based on your country legal restriction. Currently it supports only the channels 1-11 • The Random Wifi Password during the commissioning process will no change randomly after the screen goes in standby mode
M22401-W M22403-W M22401-W-03 M22401-W-04	1.11	19/07/2021	<ul style="list-style-type: none"> • Improve video transmission quality in network environments with low bandwidth reliability • Number of push notifications has been reduced. Users used to receive two identical push notifications for an incoming door call or event. These multiple notifications have been reduced to one push message per event. • Customers now only receive push notifications associated with the Welcome app. The behavior of push notifications has been improved. Customers previously receive push notifications for each event that occurs in the local Welcome system. For example, when the door is opened from another indoor station. The behavior has been improved with this release.
M22401-W M22403-W M22401-W-03 M22401-W-04	1.10	26/02/2021	<ul style="list-style-type: none"> • Improve video transmission quality when transferring to Welcome App
M22401-W M22403-W M22401-W-03 M22401-W-04	1.09	20/01/2021	<ul style="list-style-type: none"> • The LED backlight of the touch keys remained on after successful complete startup. This behavior has been corrected with this version.

HAUS- UND GEBÄUDEAUTOMATION

Softwareinformation

Video Innenstation 4.3 WLAN

Produktname	Video indoor station 4.3 WLAN
Produkttyp	M22401-W, M22403-W, M22401-W-03, M22401-W-04
Bestellnummer	2TMA220050W0022, 2TMA220050W0024, 2TMA220050W0026, 2TMA200051W0001
Aktuelle Version	Firmware Update, 08/12/2021

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	Firmware
M22401-W	2TMA220050W0022	Link	V1.12 update via Welcome App
M22403-W	2TMA220050W0024	Link	
M22401-W-03	2TMA220050W0026	Link	
M22401-W-04	2TMA200051W0001	Link	

BEMERKUNG:

Wenn Ihr Gerät mit dem Internet verbunden und mit der Welcome App gekoppelt ist, dann erhalten Sie in Kürze eine Anfrage für ein automatisches Software Update

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

FIRMWARE

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
M22401-W M22403-W M22401-W-03 M22401-W-04	1.12	08/12/2021	<ul style="list-style-type: none"> • Während des Paring-Prozesses sendet die Welcome App die myBuildings Portal Anmeldedaten automatisch an die Wifi Indoor Station • Basierend auf der Länderauswahl Ihres Smartphones wird die Wifi Indoor Station zusätzlich die Kanäle 12 und 13 aktivieren, je nach den gesetzlichen Einschränkungen Ihres Landes. Derzeit unterstützt sie nur die Kanäle 1-11 • Das zufällige Wifi-Passwort während der Inbetriebnahme ändert sich nicht mehr, wenn der Bildschirm in den Standby-Modus geht
M22401-W M22403-W M22401-W-03 M22401-W-04	1.11	19/07/2021	<ul style="list-style-type: none"> • Verbesserung der Videoübertragungsqualität in Netzwerkumgebungen mit geringer Bandbreitenzuverlässigkeit • Anzahl der Push Benachrichtigungen wurden reduziert. Benutzer erhielten bisher bei einem eingehenden Türruf oder Ereignis immer zwei identische Push Benachrichtigungen. Diese Mehrfachbenachrichtigungen wurden auf eine Push Nachricht pro Event reduziert. • Kunden erhalten nur noch der Welcome App zugeordneten Push Benachrichtigungen. Kunden erhalten bisher für jedes Ereignis, das im lokalen Welcome System eintritt, eine Push-Benachrichtigungen. Beispielsweise wenn von einer anderen Innenstation die Tür geöffnet wird. Das Verhalten wurde mit dieser Version verbessert. Kunden erhalten nur noch der Welcome App zugeordneten Push Benachrichtigungen.
M22401-W M22403-W M22401-W-03 M22401-W-04	1.10	26/02/2021	<ul style="list-style-type: none"> • Verbesserung der Videoübertragungsqualität bei der Übertragung zu Welcome App
M22401-W M22403-W M22401-W-03 M22401-W-04	1.09	20/01/2021	<ul style="list-style-type: none"> • Die LED Hintergrundbeleuchtung der touch Tasten blieben nach erfolgreicher vollständigen Inbetriebnahme weiterhin eingeschaltet. Dieses Verhalten wurden mit dieser Version korrigiert.