

MicroSCADA Pro SYS600 9.4 Hotfix 1 Release Note

Products

MicroSCADA Pro SYS600 9.4

Description

The Hotfix includes corrections for the following communication issues:

- 1. Modbus TCP Master - Incorrect command handling**
The command sending is incorrect in a configuration where several IEDs are connected to the same Modbus line and these IEDs have the same Modbus addresses separated only with the IED specific IP-address. **In worst case the command can be sent to the wrong IED.**

MicroSCADA Pro SYS600 9.4 Hotfix 1 Release Note

Dependencies

This Hotfix should only be used with SYS600 9.4.

Recommendation

It is recommended to install this Hotfix in all SYS600 9.4 systems.

Installation

To install the Hotfix:

1. Stop the SYS600 system
2. Run the installation program SYS600_94_HF1.exe
Note! In Windows Server 2003 the installation must be started by using the Windows Add or Remove Programs utility.

The Hotfix will install the following new files or file versions:

sc\prog\pc_net\pc_nets.exe	
----------------------------	--

To uninstall the Hotfix:

1. Stop the SYS600 system
2. Run the installation program SYS600_94_HF1.exe /r
3. Re-install the main product SYS600 9.4.