



Door interlock
Safety relay to monitor the GKey switch.

* Use a separate cable for the unlock signal when there is a risk of short circuit in the cable to the switch

			Datum	2018-12-19	ABB	ABB Jokab Safety	GKey_Vital1_2TLC010023T0005	= GKey
			Redigerare	SEHAHAL5	New products			+
			Kontrollerad					
Ändring	Datum	Namn	Ursprung		Ersättning for	Ersatt av		Blad 13
							HHg_New	Blad 22 / 23