



Maintenance Schedule

4FPS10000027040

Issued by	Date	Language	Revision	Page
ABB Oy, Product Support	11.01.2012	en	A	1 (1)
Creator name	Distribution		Public	
Kimmo Hirvonen				

9C Series AC Servomotors

Legend:	
Inspection (visual inspection, correction and replacement if needed)	I
Performance of on-site work (commissioning, tests, measurements, etc.)	P

	Years from start-up																					
	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21
Start-up	P																					
Cooling																						
➤ Check that motor surface is clean to ensure proper cooling of the motor. Clean the motor surface if needed		I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I
Operational Conditions																						
➤ Check the general condition of the motor mounting and bearing (detect abnormal vibrations, heat or noisiness)		I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I
➤ Check the tightness of the cable connectors (power and signal cable connectors)		I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I
➤ Check the motor cleanness, corrosion and temperature		I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I
Environmental conditions																						
➤ Humidity level, dustiness and ambient temperature		I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I
Improvements																						
➤ Based on product notes		I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I
Spare Parts																						
➤ Spare Parts		I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I	I

Note! Recommended service intervals are based on the operational environment specified by ABB. **ABB recommends an annual drive inspection to be carried out in order to secure best reliability and optimum performance.** Please refer to service instructions and product manuals for more information or go to www.abb.com/drivesservices.