

Important software update

PCCU32 7.69 and 7.69.1 production releases discontinued

21 MAY 2021 | 2107633TB-TB219

Description

The PCCU versions described below contain bugs that may impact the systems, PCs or laptops where the PCCU software is installed. This bug occurs when PCCU is disconnected or closed after a previously established connection with ABB remote controllers, flow computers and NGCs.

Is your product impacted?

This issue is present if any of the following PCCU software versions are used:

- PCCU 7.69 Production Release
- PCCU 7.69.1 Production Release

Resolution

ABB recommends that you stop using any of the versions above if they have been installed on your computer. In addition, if your system already has any of these versions, please remove it immediately and install [PCCU version 7.70.1](#) which will fix this problem. The latest PCCU version is always available at the [ABB library download center](#).



ABB Inc.

Measurement & Analytics

Quotes: US-IAMA.inquiry@us.abb.com

Orders: US-IAMA.order@us.abb.com

Training: US-IAMA.training@us.abb.com

Support: upstream.support@us.abb.com

+1 800 442 3097 (opt. 2)

Additional free publications are available for download at:

www.abb.com/upstream

Main Office - Bartlesville

7051 Industrial Blvd
Bartlesville, OK 74006
Ph: +1 918 338 4888

Kansas Office - Liberal

2705 Centennial Blvd
Liberal, KS 67901
Ph: +1 620 626 4350

Texas Office - Houston

3700 W. Sam Houston
Parkway S., Suite 600
Houston, TX 77042
Ph: +1 713 587 8000

Texas Office – Odessa

8007 East Business 20
Odessa, TX 79765
Ph: +1 432 272 1173

Texas Office – Pleasanton

150 Eagle Ford Road
Pleasanton, TX 78064
Ph: +1 830 569 8062

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents - in whole or in parts - is forbidden without prior written consent of ABB.

2107633TB-TB219

Copyright© 2021 ABB all rights reserved