

Content

1 Device - Revision Record - What is new? 1

1.1 Hardware ID: 3434..... 1

1.2 Firmware 1

1.3 Device 1

2 Cyber Security info..... 1

2.1 ABB recommendation..... 1

3 DTM (Device Type Manager)..... 2

3.1 Supported devices 2

3.2 DTM (driver) Version record - What is new? 2

3.3 Requirements..... 2

3.4 Installation and configuration..... 2

3.5 Update- / Upgrade instructions..... 2

3.6 Known problems and limitations 2

3.7 Getting help / further information..... 2

3.8 How to get the latest information & software? 2

3.9 Licensing the DTM..... 2

4 EDD..... 2

4.1 Supported devices 2

4.2 EDD Version record / What is new?..... 2

4.3 Requirements..... 2

4.4 Installation and configuration..... 2

4.5 Known problems and limitations 2

4.6 Getting help / further information..... 2

4.7 How to get the latest information & software? 2

5 GSD..... 3

5.1 Supported devices 3

5.2 GSD Version record / What is new? 3

5.3 Requirements..... 3

5.4 Installation and configuration..... 3

5.5 Known problems and limitations 3

5.6 Getting help / further information..... 3

5.7 How to get the latest information & software? 3

6 FDI Package (EDD based)..... 4

6.1 Supported devices 4

6.2 FDI ABB.Package Version record - What is new? 4

6.3 Supported Languages 4

6.4 Requirements..... 4

6.5 Import / remove and configuration 4

6.6 Update- / Upgrade instructions..... 4

6.7 Known problems and limitations 4

6.8 Getting help / further information..... 4

6.9 How to get the latest information & software? 4

- *) DTM500 Bundle Supplement Info is available on the data medium \documentation or latest on www.abb.com/fieldbus. Enter here in the search field following No. "3KXD801500R3901".

1 Device - Revision Record - What is new?

1.1 Hardware ID: 3434

| Released Revision | Released Datum | Remarks |
|-------------------|----------------|---------------|
| 01.00.00 | April 2018 | First release |

1.2 Firmware

| Released Revision | Released Datum | Remarks |
|-------------------|----------------|---------------|
| 00.05.01 | April 2018 | First release |

1.3 Device

| Released Revision | Released Date | Remarks |
|-------------------|---------------|---------------|
| 01 | April 2018 | First release |

2 Cyber Security info

2.1 ABB recommendation

A virus scanner shall be used on all PCs/Notebooks. McAfee VirusScan® Enterprise has been tested and qualified for this purpose.

3 DTM (Device Type Manager)

3.1 Supported devices

CoriolisMaster FCB4xx, FCH4xx, FCT4xx

3.2 DTM (driver) Version record - What is new?

| Released driver Version | Released Date | Released bundle / Library Version | Remarks |
|-------------------------|---------------|-----------------------------------|--|
| 05.00.00 | April 2018 | ≥ 05.05.00 / ≥ 05.00.22 | - First release - Part of the DTM500 Bundle |
| 05.00.01 | June 2019 | ≥ 05.05.00 / ≥ 05.00.22 | - Bug fixing |

- The device DTM supports the standard FDT 1.2 / 1.2.1.

3.3 Requirements

3.3.1 PC-Hardware, Operating system

See DTM500 Bundle Supplement Info*)

3.3.2 Frame application / compatibility

See DTM500 Bundle Supplement Info*)

3.4 Installation and configuration

3.4.1 Installation

See DTM500 Bundle Supplement Info*)

3.4.2 Uninstall instructions

See DTM500 Bundle Supplement Info*)

3.5 Update- / Upgrade instructions

See DTM500 Bundle Supplement Info*)

3.6 Known problems and limitations

None known

3.7 Getting help / further information

- Press 'F1' for DTM online help.
- Help concerning the integration of the DTM in the FDT frame application can be found in the respective documentation of the frame application.

3.8 How to get the latest information & software?

The latest device driver Supplement Info & software (driver) is available on www.abb.com/fieldbus:

- latest information [*field device protocol dependent*]
- latest info (download) [*device type dependent*]
- Driver description
- Software [*driver type dependent*]

3.9 Licensing the DTM

See DTM500 Bundle Supplement Info*)

4 EDD

4.1 Supported devices

Profibus DP CoriolisMaster
 FCB4xx, FCT4xx, FCH4xx

4.2 EDD Version record / What is new?

| Released Version | Released Date | Remarks |
|------------------|---------------|--------------------------------|
| 0101 | April 2018 | First Release for Siemens only |

4.3 Requirements

4.3.1 Interpreter / compatibility

The EDD is released for PDM .

4.4 Installation and configuration

Start your Frame application and follow the instructions.

4.5 Known problems and limitations

- None known

4.6 Getting help / further information

- Help concerning the integration of the driver in the frame application can be found in the respective documentation of the frame application.

4.7 How to get the latest information & software?

The latest device driver Supplement Info & software (driver) is available on www.abb.com/fieldbus:

- latest information [*field device protocol dependent*]
- latest info (download) [*device type dependent*]
- Driver description
- Software [*driver type dependent*]

5 GSD

5.1 Supported devices

Profibus DP CoriolisMaster
FCB4xx, FCT4xx, FCH4xx

5.2 GSD Version record / What is new?

ABB.3434.GSD

| Released Version | Released Date | Remarks |
|------------------|---------------|---------------|
| 010000 | Oct. 2018 | First Release |

5.3 Requirements

5.3.1 Interpreter / compatibility

5.4 Installation and configuration

Start your Frame application and follow the instructions.

5.5 Known problems and limitations

- None known

5.6 Getting help / further information

- Help concerning the integration of the driver in the frame application can be found in the respective documentation of the frame application.

5.7 How to get the latest information & software?

The latest device driver Supplement Info & software (driver) is available on www.abb.com/fieldbus:

- latest information [*field device protocol dependent*]
- latest info (download) [*device type dependent*]
 - Driver description
 - Software [*driver type dependent*]

6 FDI Package (EDD based)

6.1 Supported devices

FCB430, FCB450, FCT430, FCT450, FCH430, FCH450

6.2 FDI ABB.Package Version record - What is new?

| Released Date | Pack- age Version | EDD Released Version (Dev Rev) | Attachment (revision) | UIP Released Version (00.00.00) | UIP Changed UIP file count | Remarks (EDD, Attachment, UIP) |
|---------------|-------------------|--------------------------------|---|---------------------------------|----------------------------|--------------------------------|
| October 2018 | 01.00.00 | 01 02 | ABB_256x256.png, ABB_3434.gsd, Cor_if_256x256.png, OI_FCB400_FCH400_EN_D | no | no | First release |

6.3 Supported Languages

The device Package supports English.

6.4 Requirements

FDI Technology Version 1.x.x

6.5 Import / remove and configuration

Start your EDD Host application and follow the instructions.

6.6 Update- / Upgrade instructions

No

6.7 Known problems and limitations

No

6.8 Getting help / further information

Help concerning the integration of the Package in the FDI frame application can be found in the respective documentation of the FDI tool. Use mouse over for field hints and tooltips.

6.9 How to get the latest information & software?

Please check on FieldComm Group webpage www.fieldcommgroup.org

**ABB has Sales & Customer Support
expertise in over 100 countries worldwide.**
<http://www.abb.com/flow>

The Company's policy is one of continuous product
improvement and the right is reserved to modify the
information contained herein without notice.

Printed in the Fed. Rep. of Germany (10.2018)

© ABB 2018



Germany

ABB Automation Products GmbH
Borsigstr. 2
63755 Alzenau

Tel: +49 (0)551 905-534
Fax: +49 (0)551 905-555
vertrieb.instrumentation@de.abb.com

USA

ABB Inc.
125 E. County Line Road
Warminster, PA
18974-4995

Tel: +1 (0)215 674 6000
Fax: +1 (0)215 674 7183
instrumentation@us.abb.com

Italy

ABB S.p.A.
Via Statale 113
22016 Lenno (CO)

Tel: +39 0344 58111
Fax: +39 0344 56278
abb.instrumentation@it.abb.com

UK

ABB Limited
Oldends Lane
Stonehouse
Gloucestershire GL10 3TA

Tel: +44 (0)1453 826 661
Fax: +44 (0)1453 829 671
instrumentation@gb.abb.com

P.R. China

ABB Engineering (Shanghai) Ltd.
32 Industrial Area
Kangqiao Town, Nanhui District
Shanghai, 201319

Tel: +86 (0) 21 6105 6666
Fax: +86 (0) 21 6105 6677
china.instrumentation@cn.abb.com