

CERTIFICATE OF COMPLIANCE

Certificate Number 20160913-E48139
Report Reference E48139-19960918
Issue Date 2016-SEPTEMBER-13

Issued to: ABB Stotz-Kontakt GmbH
Eppelheimer Str 82
69123 Heidelberg GERMANY

**This is to certify that
representative samples of**

AUXILIARY DEVICES

Open-Type, Overload Relays, Types TA80DU, followed by 42, 52, 63, or 80, may be followed by M, may be followed by -V1000 for class 10; Types TA80DU, followed by 42, 52, 63, or 80, may be followed by M for class 20.

Open-Type, Terminal Block Adapter, DB80.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 60947-1 and CSA C22.2 NO. 60947-1-13, LOW-VOLTAGE SWITCHGEAR AND CONTROLGEAR - PART 1: GENERAL RULES

UL 60947-4-1 and CSA C22.2 NO. 60947-4-1-14, LOW-VOLTAGE SWITCHGEAR AND CONTROLGEAR - PART 4-1: CONTACTORS AND MOTOR-STARTERS - ELECTROMECHANICAL CONTACTORS AND MOTOR-STARTERS

Additional Information:

See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

