
CYLON® TECHNICAL BULLETIN NO. 515

Issue Date: 17 April 2023

CB Line Firmware 9.2.3

Products Affected: CBT-3T6-5R, CBV-2U4-3T, CBV-2U4-3T-N, CBX-8R8, CBX-8R8-H, CBT-4T4-2U1R

Summary

Enhancement release with updates to the FusionAir Module and some bug fixes.

Features

RESOLVED ISSUES

- Requesting the strategy size during a strategy pull or push no longer takes an excessive amount of time.
- FusionAir Module Setpoint overrides are now permanent if the Setpoint Override Time variable is set to 65535 (-1).

Customer Impact

Customers wishing to access the new functionality must upgrade when as soon as convenient.

The firmware can be download from our support web sites:

- North America <https://cyloncommunity.com/>
- Europe/ROW <http://support.cylon.com/>