

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L140448-41-22600202-1
Report Reference E140448-20200622
Date 13-Apr-2022

Issued to: ABB Stotz-Kontakt GmbH
Hauptstrasse 14-16 Hornberg 78132
Germany

This is to certify that representative samples of NKCR7 - Auxiliary Devices Certified for Canada
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.


Standard(s) for Safety: CSA C22.2 NO. 60947-1-13, 2nd Ed., Issue Date: 2013-07-31, CSA C22.2 NO. 60947-5-1-14, 1st Ed., Issue Date: 2014-03-01

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC




Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>

CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L140448-41-22600202-1
Report Reference E140448-20200622
Date 13-Apr-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
CM-TCN.012X	Auxiliary Devices
Series CM-TCN.011X, See Nomenclature Breakdown for details.	Auxiliary Devices



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>