



BUILDING AND HOME AUTOMATION SOLUTIONS

ABB-Welcome IP

Release Note Firmware

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

<https://new.abb.com/low-voltage/products/building-automation/product-range/abb-welcome>

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

ABB-Welcome IP

Release Note Firmware

Product name	IP touch 10" with TPM --- HGI17-CS (View Website)
Product type	H8327 (IP touch 10")
Order code	2TMA130050W0054 2TMA130050B0054 2TMA130050W0055 2TMA130050B0055 2TMA130050W0058 2TMA130050B0058 2TMA130050W0060 2TMA130050B0060 2TMA130051W0004 2TMA130051B0002 2TMA130051W0003 2TMA130051B0003

Latest change Firmware Update, November 2021

Current Status:

Product Type	Order Code	Website	Firmware
H8327	2TMA130050W0054 2TMA130050B0054 2TMA130050W0055 2TMA130050B0055 2TMA130050W0058 2TMA130050B0058 2TMA130050W0060 2TMA130050B0060 2TMA130051W0004 2TMA130051B0002 2TMA130051W0003 2TMA130051B0003	Link	Firmware: 2.18



NOTE:

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

FIRMWARE

Product Type	Version	Release Date	Updates and Release Notes
H8327	V2.18	November 2021	<ul style="list-style-type: none">• The HomeConnect devices connected in free@home can now displayed in the panel.• Activation of the internal RTC temperature sensor of the panel for the free@home system. The room temperature can now be integrated into free@home and used for other functions.• Improved free@home integration.• Various translation improvements
H8327	V2.10	December 2020	<ul style="list-style-type: none">• Added KNXnet/IP Secure feature, which is the secure alternative of KNXnet/IP feature.• Various improvements

HAUS- UND GEBÄUDEAUTOMATION

ABB-Welcome IP

Freigabemitteilung Firmware

Produktname	IP touch 10" with TPM --- HGI17-CS (View Website)
Produkttyp	H8327
Bestellnummer	2TMA130050W0054 2TMA130050B0054 2TMA130050W0055 2TMA130050B0055 2TMA130050W0058 2TMA130050B0058 2TMA130050W0060 2TMA130050B0060 2TMA130051W0004 2TMA130051B0002 2TMA130051W0003 2TMA130051B0003

Aktuelle Version Firmware Update, November 2021

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	Firmware
H8327	2TMA130050W0054 2TMA130050B0054 2TMA130050W0055 2TMA130050B0055 2TMA130050W0058 2TMA130050B0058 2TMA130050W0060 2TMA130050B0060 2TMA130051W0004 2TMA130051B0002 2TMA130051W0003 2TMA130051B0003	Link	Firmware: 2.18

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

FIRMWARE

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
H8327	V2.18	November 2021	<ul style="list-style-type: none">• Die in free@home angeschlossenen HomeConnect-Geräte können nun im Panel angezeigt werden.• Aktivierung des internen RTC-Temperatursensors des Panels für das free@home System. Die Raumtemperatur kann nun in free@home integriert und für andere Funktionen verwendet werden.• Verbesserte free@home Integration.• Verschiedene Verbesserungen der Übersetzung
H8327	V2.10	Dezember 2020	<ul style="list-style-type: none">• Hinzufügen der Funktion KNXnet/IP Secure, die eine sichere Alternative zur KNXnet/IP-Funktion darstellt.• Verschiedene Verbesserungen