

ABB	Lifecycle Status Statement			DOCLCM05SM001
Issued by	Date	Language	Revision	Page
ABB PID/SD, Sales Support	22.11.2004	en	A	1 (1)
Creator name	Karl-Heinz Ahl		Distribution	Public

05 SM.. Servo Drives

1. CURRENT LIFECYCLE STATUS

The 05 SM.. drive product has been in the obsolete phase since the beginning of 2005 according to the ABB lifecycle model outlined below.

2. SUPPORT AVAILABILITY FOR 05 SM..

During the obsolete phase ABB can not guarantee availability of product support within reasonable cost or technically:

- Sale of 05 SM.. parts is limited to available inventory.
- Sale of 05 SM.. repair services is limited to component availability.

3. RECOMMENDED ACTION

It is recommended that 05 SM.. drive product customers migrate to replacement products.

For a suitable replacement solution please contact us.

[Use the Link below](#) and give us Information about the existing installation, as much as possible.

4. FURTHER INFORMATION

For further information please contact mailto:Parts-Repair-LPH_DEPID/DE/ABB@ABB_DE01

5. ABB LIFECYCLE MODEL

