

ABB-secure@home

Release Note Firmware

Product name	ABB-secure@home Central Units (View Website)
Product types	SAS-W1.1E / SAS-W1.11E SAS-W1.1F / SAS-W1.11F SAS-W2.1E / SAS-W2.11E SAS-W2.1F / SAS-W2.11F
Current version	Firmware: 0.18.3-33 (Download here)

ABB releases the firmware 0.18.3-33 for ABB-secure@home security line control panels. Installation is recommended on all secure@home systems, especially for the ones equipped with GSM.

Central Unit Firmware 0.18.3-33

Bugfix

- Several stability improvements for GSM
- Bugfixes

NOTICE:

The firmware 0.18.3-33 resets all the events saved in the *Event History*, both in the *Installer* and *User* menu. It is recommended to save a backup of the system if it is intended to have the Event History available after the update.

FIRMWARE HISTORY

Product Type	Version	Since	Updates and Release Notes
Central Unit Firmware	1.18.3-33	06/2020	Update
Central Unit Firmware	0.16.54-33	01/2019	Update
Central Unit Gateway Firmware	2.3	01/2019	Update
Central Unit Firmware	1.16.50	12/2019	Update
Central Unit Gateway Firmware	2.1	12/2019	Update
Central Unit Firmware	1.16.18	09/2019	Market Introduction
Central Unit Gateway Firmware	1.255	09/2019	Market Introduction

Installation Instructions

1. Central Unit Firmware
Please follow instructions on the Central Unit Quick Guide on paragraph 7 (included in the packaging) or [ABB-secure@home system manual](#) on paragraph 13.2.7
2. Central Unit Gateway
Please follow instructions on the ABB-free@home system manual paragraph 5.7.6