

<b>ABB</b>	Lifecycle Status Statement			DOCLCMPSD8001
Issued by	Date	Language	Revision	Page
ABB ATG/SE, Sales Support	08.05.2009	en	C	1 (1)
Creator name	Karl-Heinz Ahl		Distribution	Public

## PSD / PAD 800 DC Drives (VERITRON®)

### 1. CURRENT LIFECYCLE STATUS

The PSD / PAD 8.. drive product has been in the obsolete phase since the beginning of the year 2009 according to the ABB lifecycle model outlined below.

### 2. SUPPORT AVAILABILITY FOR PSD / PAD 8..

During the obsolete phase ABB can not guarantee availability of product support within reasonable cost or technically:

- Sale of PSD / PAD 8.. parts is limited to available inventory.
- Sale of PSD / PAD 8.. repair services is limited to component availability.

### 3. RECOMMENDED ACTION

It is recommended that PSD / PAD 8.. drive product customers migrate to replacement products.


As suitable replacement possibilities of the PSD / PAD 8.. ranges we recommend:

- DCS 400 series
- DCS 800 series
- or DCR 800 rebuilt kit.

### 4. FURTHER INFORMATION

For further information, please contact ABB by e-mail: [global.productsupport@fi.abb.com](mailto:global.productsupport@fi.abb.com).

### 5. ABB LIFECYCLE MODEL



Specifications subject to change without notice.