


# Certificate of Compliance

Certificate Number 110105-E48139A  
Report Reference E48139, February 24, 2004  
Issue Date 2005 January 11

Page 1 of 1



*Issued to:* **ABB Control Inc.**

1206 Hatton Road  
Wichita Falls, TX 76302

*This is to certify that  
representative samples of*


**Open-type N22, N31, N33/11, N40, N44E, N53E,  
N62E, N71E, N80E and NL22E, NL31E, NL33/11, NL40E, NL44E, NL53E,  
NL62E, NL71E, NL80E.**

*Have been investigated by Underwriters Laboratories Inc.® in  
accordance with the Standard(s) indicated on this Certificate.*

*Standard(s) for Safety:* UL 508, Industrial Control Equipment.

*Additional Information:* The devices are open type, normally open or normally closed four and eight pole auxiliary contactors for use in control circuit of magnetic motor controllers and the like.

Only those products bearing the UL Listing Mark should be considered as being covered by UL's Listing and Follow-Up Service.

The UL Listing Mark generally includes the following elements: the symbol UL in a circle:  with the word "LISTED"; a control number (may be alphanumeric) assigned by UL; and the product category name (product identifier) as indicated in the appropriate UL Directory.

**Look for the UL Listing Mark on the product**

Issued by: *Joseph Wisnewski*  
**Joseph Wisnewski**  
Underwriters Laboratories Inc.

Reviewed by: *Bob Gill*  
**Bob Gill**  
Underwriters Laboratories Inc.